## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:				
Grand Traverse (County)	Located In	Corner Code #		
Public Land Survey	T_26N_R_10W_	K10		
Property Controlling in Section	TR S T R	- F.		
	s T R			
3. Miscellaneous	s T R			
Property in Section	S T R		Register of Deeds Stamp & File Number	
4. Lot No:				
5. Private Claims:		A B C D E F		
C. I Troub Statistics			2 - 6 - 5 - 4 - 3 - 2 - 1 - 1	
I, <u>Craig W. McVean</u> , in a field survey on <u>November 4</u> , <u>2009</u> do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			3 4 7 8 9 10 11 12	
			5	
			6 18 17 16 15 14 13	
			7	
			8 -19 -20 -21 -22 -23 -24 -	
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.		and range, may	10 30 29 28 27 26 25	
			11	
			12 31 32 33 34 35 36	
			13	
A. Description of original monument and accessories and/or subsequent restoration:				
- 1933 – M. Schaa - 1963 – DNR Land midpoint on line I nearly in line with	between section corners. Unable n old fence West. – Set 1" pipe wit ox – Property Sketch, file No. 78-2	This corner was establish to locate anything for a p th 4" brass cap, 3) 7" J. P	ned while making a survey of Section 25. Set corner previous corner and nothing definite for USBTS. Falls Pine N22°W 38.6', 4) 14" W. Oak N53°E 32.5'. und 3) 7" J. Pine N22°W 38.6',	
B. Description of corner	evidence found and/or method ap	oplied in restoring or re-e	establishing corner:	
E-W. Found withe compares to 2641	ess #4 fitting position.  No evidenc .32' – GLO, 2641.4' – Ostling, - 26 2641.4' – Ostling. Found 1" X 4½'	e of GLO BT's or Schaaf 641.40' - Wilcox. Distand	e with 4" Dept. of Conservation brass cap, in fence line f position. Distance to 'K9' measures 2640.72'-grid ce to 'K11' measures 2633.56'-grid compares to cap accepted as a careful and faithful reestablishment	
C. Description of monur	ment for corner and accessories e	stablished to perpetuate	locating the position of the corner:	
N54*E 32.96' to se S05°W 5.52' to se S87°W 47.47' to se	irsonite Post 1.5 North et nail & tag in NW side 24" W. Oa et nail & tag in E side 3" Beech et nail & tag in S side 36" W. Pine et nail & tag in SW side 4" Oak so	ak scribed 'XBT' (#4)	CRAIG W.  PROFESSIONAL SURVEYOR	
Signed by: Surveyor's Michigan	20 10 Mal	Date:	1/6/2011 PAROFESSIONAL SUFFI	
		•		