

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Grand Traverse Located In _____ Corner Code # _____
(County)

1. Public Land Survey T _____ R _____
T _____ R _____
2. Property Controlling in Section S 22 T 26N R 10W 4
S 22 T 26N R 10W 5
3. Miscellaneous Property in Section S _____ T _____ R _____
S _____ T _____ R _____

4. Lot No: _____ Recorded Plat: _____

5. Private Claims: _____

I, Craig W. McVean, in a field survey on Nov. 3, 2009 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

Register of Deeds Stamp & File Number

A. Description of original monument and accessories and/or subsequent restoration:

4 - None

5 - None



B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4 - NW 1/16 Cor. Sec. 22 - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure.

5 - CN 1/16 Cor. Sec. 22 - Set 2" Alum. Cap on 5/8" x 34" rebar per Standard BLM procedure.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

4 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
N43°W 11.61' to set N & T in NE side 13" Oak
S77°E 12.89' to set N & T in N. side 17" R. Pine
S24°E 16.37' to set N & T in E. side 16" R. Pine
S37°W 15.59' to set N & T in SE side 21" W. Pine
Set Blue Carsonite Post with Loc. tag 1' SE

5 - Stamped 2" Alum. Cap on 5/8" x 34" iron rebar
N36°E 12.91' to set N & T in NW side 3" R. Pine
S75°E 11.50' to set N & T in N. side 5" W. Oak
S16°W 26.93' to set N & T in E. side 10" R. Pine
S87°W 12.22' to set N & T in S. side 5" W. Pine
Set Blue Carsonite Post with loc. tag 1' SE

Signed by:

Craig W. McVean

Date:

1/17/2012

Surveyor's Michigan License No.:

39088