

MAR 16 1994

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
GRAND TRAVERSE
(County)

Located In: Corner Code ##

- | | | | | | |
|------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 26N | R | 11W | E-7 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | | T | R | |
| | S | | T | R | |
| 3. Miscellaneous | S | | T | R | |
| Property in Sec. | S | | T | R | |

STATE OF MICHIGAN
GRAND TRAVERSE COUNTY
RECORDED
30 DEC 93 10:19 A.M.
KARON ANDERSON
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, **Gary G. Wilson**, in a field survey on **December 17**, 19 **93**, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-7: Original G.L.O. notes and witnesses.

In 1917, Waterman references stone & iron to S.W. corner of Townhall and fence corner; both are missing (Per Liber 10, Pg. 12). Waterman measured East line as 5275 ft.; current measure is 5276.8 ft. Act 74 by W. Batzer in Sept. 1972 (Liber 1, Pg. 384) reports iron bar in monument box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-7: No physical evidence of the original GLO witnesses were found.

Found 1" iron bar in monument box 4.5 ft. East of centerline as noted on **M.D.O.T. highway map.**

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-7: Corner common to Sections 16, 17, 20 & 21

Perpetuated with 2-1/2" X 30" flanged bottom galvanized iron pipe with 3-1/2" brass cap stamped **GRAND TRAVERSE COUNTY REMONUMENTATION.**

N46°E 75.97' 16" W. Cherry
S27°E 101.02' 24" Chinese Elm
S73°W 79.78' Power Pole
N73°W 142.35' Power Pole

Corner approved by the Grand Traverse County Peer Review Group on 11-03-93.

Signed by **Gary G. Wilson, PS**
Surveyor's Michigan License No. **25881**

Date **December 28, 1993**

