## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Grand Traverse	Loc	ated In	Corner Co	ode#				
(County)		atou III	Comor Co	, <b></b>				
1. Public Land Survey	T 27 T 28	N R 9W N R 9W	L-1 L-13	<del></del>			·	
Property Controlling in Section	s T			<del></del>				
Miscellaneous     Property in Section	S T S T	R R			Registe	r of Deeds Stamp	& File Number	
4. Lot No:	Recorded Plat:							
5. Private Claims:					A B C D	E F G H /	J K L M	
I, Craig W. McVean, in a fier requirements of PA 74, Micland 2 above were in conformathe current manual of survinterior, Bureau of Land Man corner points mentioned in lift of the Michigan Board of established, re-established, re-establish	higan PA of 1970, the mance with regulation ey instructions of the magement or by a de- ines 3, 4 and 5 abov Land Surveyors or	ne corner points ins and rules their the United States cree of a Court of were in conform by a Decree of	mentioned in refore as req Department Law and/or the mance with the of a Court of	lines 1 uired in of the that the rules of Law:	3 4 - 7 - 8 - 5 6 - 18 - 17 - 7 8 - 19 - 20			
NOTE: Not more than 2 corners, all in the same town and range, be recorded on this certificate.				nay	10 30 -29 11 12 -31 -32 -	-2827	-2625 -3536	
A. Description of original r	monument and ac	cessories and/o	r subseque	nt restoration	ı <b>:</b>			
1&L-13 – Set ¼ post – L. Lyon –1850 Hem. 12" N32°W 37 L., Hem. 9" S14°E 10 L L.2 , pg. 164- E.H Aylln –1904 –said to be marked with piece of 'T' rail - L.2 , pg.368 – E. P Waterman –1909 cedar stake and iron Water pipe 30" X 1 ½ " sugar 24" N17¾°E 68.4', Sugar 6" N75 ¼ °W 154.2' this iron is also 6.2' South			ked with	<ul> <li>Unrecorded survey by Gourdie, Miller, Fraser &amp; Associates project #70244 –1970-set mon. by Sawyer wits.</li> <li>LCRC L.2 pg.485 – C.F. Roser –1982 found &amp; accepted Rd. conc. mon. previously used &amp; wit. by RLS G. Delamater. Fits Waterman's survey of 1909. Rerod with RLS cap #13030 North 32.92', 15" Tw. Ash N15°E 49.20', 40" Maple N20°E 67.60', 24" Maple N75°E 25.90' Ctr E-W gravel Rd S 3' +/-</li> </ul>			RLS RLS	
B. Description of corner ev	vidence found and	or method app	lies in resto	ring or re-est	ablishing corner:			
deep – per ⊑. with pipe. Wa	orner common to S ar surface in E-W P Waterman- 1.06 aterman say's pipe cepted as a carefu	gravel Rd. per ( ' S. & 0.54'E. o : is 6.2' S. of str	GMF&A and f concrete naight line be	Roser. Ren non. position etween K1 to	noved concrete m . Also found Wat .M1. we calculate	on. and found 1 erman's NE. Ma 5.37' S. Iron n	1 ½ " iron pipe-3	
C. Description of monume	nt for corner and a	ccessories esta	ablished to p	perpetuate lo	cating the position	n of the corner:		
1&L-13 - Raised 1 ½ " ir of stones - dov N17°E 68.43 N7°E 51.55 N66°E 26.61 S38°W 31.22 S2°W 32.33	ron pipe with 3 1/4 "	'Grand Travers W side of 40" W side of Tw NW side of 2: NW side of 1: broken conc.	se Co.' bras ' S. Maple . 28" Ash 4" S. Maple 3" R. Oak mon.	s cap on 2 ½ (EPW,CFR (CFR)	" X 30" galvanize	ed iron pipe in a	CRAIG W. MCVEAN ROFESSIONAL SURVEYOR	OR *
Signed by: Surveyor's Michigan Lice	<u>A</u>	Nu Va 39088		Date:	12/13/199		No. 39088 POFESSIONAL	