LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Grand Traverse (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>27N_R_9W</u> TR	<u> -5</u>	
2. Property Controlling	S TR		
in Section	S TR		
3. Miscellaneous	S TR		
Property in Sec.	S TR	<u></u>	Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		ABCDEFGHIJKLM
5. Private Claims			2 6 5 4 3 2 1
I, <u>Craig W. McVean</u> , in a under requirements of P.A. 74, N lines 1 and 2 above were in conferequired in the current manual of of the Interior, Bureau of Land Mathat the corner points mentioned the rules of the Michigan Board of established, re-established, month	flichigan P.A. of 1970, the corner ormance with regulations and rule survey instructions of the United anagement or by a decree of a C in lines 3, 4 and 5 above were in of Land Surveyors or by a Decree	points mentioned in es therefore as States Department ourt of Law and /or conformance with of a Court of Law;	3 4 - 7 - 8 - 9 - 10 - 11 - 12 - 5 5 - 18 - 17 - 16 - 15 - 14 - 13 - 7 8 - 19 - 20 - 21 - 22 - 23 - 24 - 9
NATE N			10 30 29 28 27 - 26 25
	corners, all in the same tow	n and range, may be recorded on	11 11 11 11 11 11 11 11 11 11 11 11 11
this certificate.			12 31 32 33 34 35 36
 1967, Consumers P. 1991 - LCRC L.3, pg.: S46°E 17" Maple 49.: S66°W 30" Maple 64. 1998, LCRC L.3, pg.8 Maple 24" S40°E 49. 	Co P. Perla set 1 ¼" iron, 349 - R. Mitchell- fnd stake a 18', N48°E 24" Maple 47.0 .58,' N36°W 1 ¼" iron pipe 107- D. Grier Jr., set ½" X 18 16', Maple 28" N52°B	and stone, set ½" rerod capped #284 07', S18°W 28" Maple 84.6 6 6.05' 3" rebar w/cap #33978 per Mitcheli w E 47.13', Locust 6" N34°W 82.	e S35°E 55.04', 16" Maple S70°W 64.45' 417 in center of stake 61' vit30', Phone riser S55°W 77' +/-
B. Description of corner evid	lence found and/or method a	applied in restoring or reestablishing	corner:
and dug down 4' and for Slawson and Waterma - Reference point – N30	ound capped iron per Mitche in position accepted as a ca 6°W 6.05' (R) of I-5 is a p	ell on W. side of stone - 0.07' E & 0.0 reful & faithful perpetuation of the po ositon established by P.Perla, Pipe v	was removed during recent road construction
Position not in agreen	nent with historical county si	urveyor record and is not utilized as	I-5 in this survey. No monument reset.
C. Description of monument	for corner and accessories	established to perpetuate locating th	he position of the corner:
S70°E 40' to set blue ca N65°E 69.33' to set N& N42°W 82.34' to Fd,N& N50°E 46.99'to Fnd. na	arsonite post w/loc.tag T in S. side 24" S. Maple, LC #33978 in NE. side 7" loc til in SE. side 24" S.Maple (F T in SW. side 23" S.Maple (I	RM,DG),	X 30 " Galv. Iron pipe – down 0.75' OF MICHIGA CRAIG W. McVEAN PROFESSIONAL SURVEYOR NO.
Signed by 10	MI Malla		17/13/1409 C No.
Signed by <u>Chuy 7</u> Surveyor's Michigan License	vi jih ven	Date /	39088
ourreyor a micrigan License	NA 30000		
	No. <u>39088</u>		A OFF SSIONAL
	No. <u>39088</u>	FORM APPROVED BY MICHIGAN	STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED OCT., 1995