LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in BRAND TRAVERSE

Surveyor's Michigan License No. _

| (Cour | nty) | Located In: G | orner Code ## | |
|---------------------------------------|---------------------------------------|---|--|--------------------------------------|
| 1. Public Land | Survey | T _ 27N_ R _9N | H-4 | |
| | · | T R | | •• |
| | | T R | | |
| 2. Property Co | | <u> 12 </u> | 13, 14 | |
| in Section 3. Miscellaneo | | T R T R | | • |
| Property in S | | T | R | egister of Deeds Stamp & File Number |
| 4. Lot No | Record | ded Plat | | · |
| 5. Private Clain | ns | | | |
| | | | | 3 1 1 1 1 1 1 1 1 |
| | | | | 4 7 8 9 10 11 12 |
| do bereby certify the | SER in a | field survey on <u>NOVENBER 3,</u> ents of P.A. 74, Michigan P.A. of 1970, | . 19 . 92 | 5 |
| in lines 1 and 2 a | bove were in confi | ormance with regulations and rules: | therefore as required in the | 6 18 17 16 15 15 17 |
| Management or by | a decree of a Cour | s of the United Stales Department of t of Law and/or that the corner points | mentioned in lines 3, 4 and 5 | 8 19 20 21 22 23 24 |
| above were in con Court of Law; es | formance with the stablished, re-esta | rules of the Michigan Board of Land S iblished, monumented, re-monume | Surveyors or by a Decree of a nled, recovered, found as | 9 |
| expressed below: | | | | 10 30 29 28 27 26 25 |
| | re than 4 corner: certificate. | s, all in the same town and rang | e, may be recorded | 11 12 31 32 33 34 35 36 |
| | | | | 13 33 34 35 36 |
| A. Description H-4 | of original monut | ment and accessories and/or sut 13 | bsequent restoration: | |
| AS CALLED OUT I BELOW.) | IN THE G.L.O. LIN | B.T'S, LINE TREES & TOPOGRAPHY, E NOTES; UNLESS NOTED IN ITEM "B" | | |
| | of corner evidend | ce found and/or method applied | in restoring or reestablishing | g corner; |
| M-4 FA REPT MAN EAR | E 1/4 COR S-12 | EN CTONE MITH CROSS CON CONTEN | 14 | |
| AS SET BY K.J. | OSTLING IN 1967 | | CHISELED "+" ON TOP BY SLA | |
| DEPT SURVEY AT | RECOVERED STONE | BATZER CERT OF SURVEY, L:2, | (1876) FOR NE COR OF SE 1/ | 4 OF |
| W/CROSS ON TOP MERRILL, 1909). | | P6 121, SAYS HE FOUND STONE PER SLAMSON 1876 & WATERMAN | SE 1/4 SEC 12. WE ADDED 1 PIPE W/COUPLING & PS CAP | • |
| GRAVEL RD IS B. | N & CTR TRAIL | 1907 (?) SURVEYS. FD OLD N-S | DIRECTLY UNDER *+* ON STON | |
| SOUTH IS 10' WE | 51. | FENCE REMAINS 25'± NEST & N-S LANE TO NORTH (DPENING IN MOODS) IS 28' WEST. | PS'S N. BATZER & R. MITCHE USED STONE IN PREVIOUS SURVEYS. CENTER OF N-S TRI IS 27' WEST. | |
| C. Description of | of monument for | corner and accessories establish | hed to perpetuate locating the | he position of the corner: |
| FD CONSERVATION | DEPT. MON | FD 7" X 7" X 14" STONE W/CROSS | FD LARGE STONE N/"+" ON TO | |
| 12" R PINE | N50°W 59.40' | ON POINT, BURIED 1" X 15" GALV PIPE W/PS CAP DIRECTLY | ADDED 1" PIPE W/PS CAP UNDE STONE & SET CED POST W/LOC | |
| 5" TW W PINE | N55°E 57.05' | UNDER POINT OF STONE. | TAG. | CARL' |
| #38" SUG MAPLE 5" R DAK | \$25°E 25.64' \$55°N 90.08' | 11" SUG MAPLE N30°N 9.58' | 3° SUG MAPLE N55°W 12. | ·01 F. ROSER |
| SET CED POST WET | | \$10° BASSSWOOD S30°E 12.36' | #7" SUG MAPLE N10°E B, #2" SUG MAPLE 560°E 9, | .98' LAND SURVEYOR |
| LOCATION TAG | NORTH 33' | #10" SUS MAPLE \$25"W 17.82" | #10" R OAK \$80°W 11. | .05 12028 |
| ANIT BY OTHERS. | - 1 | #RLS WM BATZER 1973 NIT. | *WIT BY OTHERS. | LARD SURPLIES |
| Signed by | et. No | Les 4.21.8 | 95 Date | |
| Surveyor's Michia | | 12028 | | |

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983