STATE OF MICHIGAN DEPARTMENT OF NATURAL RESOURCES

LAND CORNER RECORD

		GRAND TRAVERSE COUNTY	
		T <u>27 N</u> R T <u>26 N</u> R	
DESCRIPTION OF CORNER	1/4 corner common to Sections 3	16 & 1	
	Found Round Concrete monument.	Added Cedar Guard location tag.	Post with
DATE MONUMENT PLACED AN WITNESSES TO CORNER			
N CONNEX	••	,	
5	6" B. Cherry	N 61 E	19.5'
36	9" J. Pine	S 48 E	41.61
	AND		
CIRCLE CORNER REGISTE	ERED		<u> </u>

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was recovered while making a retracement survey in this area. John Norton and Associates found an old broken stake point, still in ground, in May 1951. They replaced the stake point with a concrete monument.

SURVEYOR'S SEAL

SIGNED

Carl F. Koren

ATE 6/16/70

DISTRIBUTION:

REGISTERED LAND SURVEYOR 12028

County Courthouse Area Forester (Regions I & II) District or Region Surveyor Forestry Div., Lansing