

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

I, Carl F. Roser, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were, in a field survey on March 23, 1976, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____, 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

11 Established center of SW $\frac{1}{4}$ of Section 13 per standard B.L.M. instructions.

13 Established center of SE $\frac{1}{4}$ Section 13 per standard B.L.M. instructions.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

4
5 Fd. 1" sq. iron as recovered in previous dept. survey for cor. comm. to Sec. 7 & 8 (27-9) & Sec. 12 & 13 (27-10) at old cor. fence post, fn. remains N & E. Recovered iron fits E.P. Waterman survey of Sec. 7 (27-9) as recorded in L. 1, pg. 515 (1907), L. 1, pg. 519 (1915) & L. 10, pg. 23 (1916) of old co. surveyors records at co. ct. house, Reg. of Deeds. Corner also fits remains of USBT (Y. Pine SE) as estab. in govt. resurvey on line between sections 7 & 8 (27-9) dated 5/20, 1850 (L. Lyon). NOTE: above listed surveys by Waterman plus Waterman survey of Sec. 13 (27-10) L. 3, pg. 380 (1917) indicate a jog of 123.42' N for corner to Sec. 12 & 13 (27-10). We fd. shadow of oak stk. bottom at 123' N of fd. 1" sq. iron but no occupancy to E or W. Orange Risdon in govt. resurvey of line between Sec. 12 &

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: (see above)

M-5			11			13		
Fd. 1" sq.iron & cedar post w/loc.tag			Set 1"x30" pipe & cedar post w/loc.tag			Set 1"x30" pipe & cedar post w/loc. tag		
20" Twin Oak	N04°W	63.4	10" Oak	N82°E	35.1	7" R. Oak	N30°E	15.5
6" W. Pine	N53°W	49.4	12" Maple	S40°W	11.2	7" R. Oak	S50°E	12.6
8" W. Pine	N74°W	32.2	8" W.Pine	N15°W	27.7	3" R. Pine	S34°W	26.2
14" Oak	S76°E	32.2						
Old Y. Pine witness stp.								
	S28°E	20.5						

SIGNED BY Carl F. Roer 4-28-77 DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. 12028

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

MICHIGAN REGISTERED LAND SURVEYOR

(SEAL)

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ GRAND TRAVERSE COUNTY

FORM APPROVED BY MICHIGAN STATE BOARD OF REGISTRATION, JAN. 28, 1971
REVISED MAY 14, 1975

MAY PLACE SKETCH ON BACK OR ATTACHED SHEET

