MAR 22 1999

LIBER 003 page 839

SECTION For corners in		RNER RECORDATION puirement of Act 74, N			E OF WICHIG TRAVERSE CI RECORDED		
	Located in:	Corner Code#		30 DEC 98 11:01 A.H.			
1. Public Land Survey	T <u>28 R 09 </u>			KARON ANDERSON REGISTER OF DEEDS			
2. Property Controlling S in Section S 3. Miscellaneous S Property in Sec. S	TR TR TR TR			Register of D	eeds Stamp	& File I	Number
4. Lot No, Recorded Plat	on November 19 of 1970, the corner perefore as required in to the sureau of Land Manages 3, 4 and 5 above were sureau of the sur	, 19 <u>98</u> do he oints mentioned in lines 1 and the current manual of survey gement or by a decree of a Co were in conformance with th	2 3 ereby state that d 2 above were instructions of burt of Law and he rules of the	7 8 -17	F G H	1 J 3 —— 2 1	1 12- 4 13- 3 24-
NOTE: Not more than 2 corners, all in to on this certificate.	ne same town and I	range, may be recorded	9 16 1 1. 1.	0 30 29 1 29 2 31 32 32 32 32 32 32 32 32 32 32 32 32 32		7	
E-1: U.S. Govt. survey by Lucius Lyon, lks., sugar 40" S58E 12 lks. County Surveyors Records recorded in County Surveyors Records recorded in G.T. County Road Commission record Gourdie, Miller, Fraser & Assoc. in 1971 Wm. B. Batzer Certificate of Survey in Lorner. Carl F. Roser, Petobego State Game A Land Corner Record in L.2, P.329 on services.	L.1, P.43 in 1891; L.1, P.311 in May. (undated, 1960's±); found iron while L.1, P. 905 in July 1 rea, DNR project r	C.P. Tuller, shows new w 1894; Steele found "rem ; "iron post", found and w doing survey for Road C 1973; found 3/4" iron pip	vitnesses but no de nains of an old stak vitnessed. commission. ne in mon. box. Lar	scription. e and some sto nd Corner Reco	ones". ord in L. 1, P	. 637.on	n same
B. Description of corner evidence four E-1: Section corner common to section Found 3/4" x 22" iron pipe over 2½" x 3 the witnesses match Roser 1978. This Remonumented this position with a 2½ REMONUMENTATION.	s 4 & 5, T28N, R09 9" railroad track sec corner is accepted x 30" flanged botto	9W and 32 &33, T29N, R gment (on end) in a mone I as a careful and faithful p om galvanized iron pipe v	R09W. ument box at the in perpetuation of a lo with a 3¼" brass ca	ng established p stamped GR	iocally acce AND TRAVI	pted cor	rher.
C. Description of monument for corner E-1: Section corner common to section Set 2½" x 30" flanged bottom galvanize monument box at the intersection of To	s 4 & 5, T28N, R09 ed iron pipe with a 3	9W and 32 &33, T29N, R 3¼" brass cap stamped G	R09W.		MONUMEN		
N 31°E 68.01′ power pole S 20°E 55.27′ power pole S 64°W 62.44′ set ½″ iron re N 61°W 163.74′ power pole	bar	UNANIMOUSLY ACCE GRAND TRAVERSE C REVIEW GROUP AS T CORNER UNDER MICH ACT 345 OF 1990 AT HELD ON 11-1	OUNTY PEER THE OFFICIAL HIGAN PUBLIC FA MEETING LOSE	The same	RANDY WENDL PROFESSI SURVEY No. 39091	M. AND ONAL OR	eron s