## SURVEY & REMONUMENTATION

APR 27 1995

003 PAGE 589

STATE OF MICHIGAN GRAND TRAVERSE COUNTY RECORDED

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

30 DEC 94 1:35 P.N.

Grand Traverse	Located In:	Corner Code ≠#	Karon Anderson Register of Deeds
1. Public Land Survey	T 29N R 10W T R T R	<u>1-8</u>	
<ol> <li>Property Controlling in Section</li> <li>Miscellaneous Property in Sec.</li> </ol>	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Rough Sprivate Claims	ecorded Plat		A B C D E F G H 1 J K L M
I, Garth D. Stowe, in a field survey on October 13, 19, 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			oned 6 18 17 16 15 14 13 14 13 16 15 14 15 14 15 14 15 14 15 16 15 16 16 16 16 16 16 16 16 16 16 16 16 16
NOTE: Not more than 4 co on this certificate.	orners, all in the same town an	d range, may be recorded	11 12 -31 -32 -33 -34 -35 -36

- A. Description of original monument and accessories and/or subsequent restoration:
- 1/4 corner common to Sections 22 & 23, T.29N., R.10W. Original G.L.O. notes and witnesses. Act 74 filed in Liber 1, Pg. 234.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner;
  - I-8: No physical evidence of original G.L.O. witnesses were found. Found 1/2" x 18" re-rod with cap #28417 within a broken concrete monument remains and replaced with Grand Traverse County monument.

UNANIMOUSLY ACCEPTED BY THE GRAND TRAVERSE COUNTY PEER REVIEW GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1960 AT A MEETING HELD ON 10-2 P.B., CHAIHMAN

Description of monument for corner and accessories established to perpetuate locating the position of the corner:  1-8: 1/4 Corner common to Sections 22 & 23, T.29N., R.10W.				
Perpetuated with 2-1/2" x 30" flanged bottom galvanized iron				
pipe with 3-1/4" brass cap stamped GRAND TRAVERSE COUNTY				
REMONUMENTATION.				
N04°E 22.69' 4" Elm	ı			
N81°E 52.43' 3" Elm GARTH	Ġ			
S13°W 97.26' 6" Clump Basswood D. STOWE	$f^{j}$			
S40°E 97.21' 3" Clump Elm	3			
S33°W 5.63' Broken concrete monument * surveyor : *				
Corner approved by the Grand Traverse County Peer Review Group, NO.	$\mathcal{H}$			
on 10-25-94, 25075 25075	Ş,			
Same of the same o	•			
igned by Date 12-29-Promonanting				
Garth D. Stowe 25875				

Surveyor's Michigan Lieense No. \_\_\_ FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAH. 28, 1971 REVISED MAY 14, 1975