

1993

COMMISSION

STATE OF MICHIGAN
COUNTY OF LEELANAU
RECEIVED FOR RECORD

1993 DEC 28 PM 4: 26

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Leelanau

(County)

Located In:

Corner Code #

- | | | |
|-------------------------|-------------|-----|
| 1. Public Land Survey | T 29N R 11W | C-1 |
| | T R | |
| | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling | S T R | |
| in Section | S T R | |
| 3. Miscellaneous | S T R | |
| Property in Sec. | S T R | |

Barbara Kirt
REGISTER OF DEEDS

FILE #337

LIBER 2 PAGE 34

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Steven P. Bye, in a field survey on December 13, 1993,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

C-1: NE corner Section 6: G.L.O. "Set post corner"
Cedar 10 N 62 W 29 links
Cedar 10 N 45 E 20 links
Cedar 9 S 78 E 29 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1: NE corner Section 6: Spike found over 1-1/4" x 1/4" iron bar (leaf spring)
at the intersection of Kohler Road and Erdt Road, and
on extension of fenceline East.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-1: NE corner Section 6: 1-1/4" x 1/4" iron bar(leaf spring) accepted by the
Leelanau County Remonumentation Peer Group, November 29,
1993, and replaced with a 3/4" i.d. galvanized iron pipe
3' long with a brass cap.

Power pole N 25 E, 78.02' (record)
12" cherry N 52 W, 83.37' (record)
Utility pole N 70 W, 99.76' (record)
Southeast corner of block garage N 52 E, 119.51'
4" tart cherry S 60 E, 63.77' (set spike)

Signed by Steven P. Bye

Date 12-20-93

Surveyor's Michigan License No. 35991

