SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

STATE OF MICHIGAN COUNTY OF LEELANAU RECEIVED FOR RECORD

1994 DEC 14 PM 2: 13

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Barbara Kirt REGISTER OF DEFOS

For corners in Leelanau Located In: Corner Code ## (County) # 376 T 29N' R 11W 1. Public Land Survey T _____ R ___ LIBER 2 PAGE 73 2. Property Controlling 3. Miscellaneous S ____ R __ Register of Deeds Stamp & File Number Property in Sec. ____, Recorded Plat ____ Private Claims

Steven P. Bye ___ in a field survey on __ November 17, 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

3 10 12 13

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
- C-11: Northwest corner of Section 32

G.L.O. notes: Set post corner to sections 29, 30, 31 & 32.

Beech 16 - S 49 E, 11 links Sugar 18 - S 66 W, 25 links Survey by Green: "Set pit cobble stone 2-1/2" deep and dark granite 14x12x10 with an "X" on top, "S.C." on side.

Telephone pole S 24 25' E, 20'

Telephone pole S 65 W, 20'

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- C-11: Northwest corner of Section 32

1/2" iron bar in monument box in centerline of County Rd. 633, traced to Brehmer's field book No. 25.

Brehmer witnesses: 10" elm - N 12 45' E, 143.3' 8" 46h - S 06 000 E, 125.0'

Electric light brace post - Easterly 30.02'

APPROVED LAND CORNER P.A. 345 OF 1990 LEELANAU COUNTY

DATE: _5-29-94

COUNTY REP. M.M.O

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- C-11: Northwest corner of Section 32

1/2" iron bar in monument box accepted by the Leelanau County Remonumnetation Peer Review Group, May 25, 1994, and replaced with a 3/4" i.d. galvanized iron pipe 3' long with a

brass cap.

Electric brace pole - East 31.50'

7" Sweet cherry - N 50 E, 95.02'

Power pole - S 25 W, 238.43'

7" Elm - North, 233.32'

teven P. Bye Date December Surveyor's Michigan License No. 35991

OF MICHIE STEVEN P BYE SURVEYOR No. FORM APPROVED BY MICHIGAN STATE BOARD OF VÍSED MÁY 14, 1975

REVISED JAN., 1983