C REMONUMENT

LIBEROO2 PAGE 163

 r A	.B.,	1.	10000

COMMISSION	LAND CORNER RE	CORDATION CERT	IFICATE		•				
For corners in	Filing Requiremen	t of Act 74, Mich. P.	A. 1970 hara	Kirt Peg of Negr	01/08/97 ds 2:34 pm				
Leelanau (County)	Located in:	Corner Code #		BJK Fe	e: 9.00				
(County)		•	04800002	P0163	Page 1 of 1				
1. Public Land Survey	T <u>29N</u> R <u>11W</u> T R T R T R	1-3	10 de						
2. Property Controlling S	T R		<u>.</u>						
3. Miscellaneous S	TR TR		#466						
Property in Section S									
4. Lot No, Record	ied Plat								
5. Private Claims				A B C D E	FGHIJKL				
			2	2 - 6 - 5 - 5					
			4	1 7 8	9 10 11 12-				
i, Steven P. Bye , in a f			5	<u> </u>	- - - - - 				
do hereby certify that under requirement in lines 1 and 2 above were in conformanual of survey instructions of the Management or by a decree of a Cout 5 above were in conformance with the Decree of a Court of Law; established as expressed below:	nance with regulations and rules the United States Department our of Law and/or that the corner phe rules of the Michigan Board of	nerefore as required in the of the Interior, Bureau of coints mentioned in lines 3, f Professional Surveyors of	current f Land f Land f and f	3029	-16 - 15 - 14 - 13 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 14				
NOTE: Not more than 4 corners, on this certificate.	all in the same town and range	e, may be recorded	11						
A. Description of original monu			13	1 7 7					
I-3: Southeast corner G.L.O. notes: "Set post corner Ced Do. County Surveyor stake found, rep Witnesses: 6" 6" 4" B. Description of corner eviden I-3: Southeast corner	r section 3 r to sections 2, 3, 1 dar 12 N3W 12 IVs. 6 S22E 09 IVs. notes stumps of origolaced with a well po Cedar West 9.05' Cedar South 5.8' Balsam 7.3' Bore found and/or method applet section 3 found by Brehmer and SE 9.0' (old wit.) CE 17.88'	O and 11." inal cedar post int by Brehmer. led in restoring or rees replaced with a	found by (tablishing con well poin APPROVED P.A. 34 LEELANA	ner: nt, recove: LAND CORI 45 OF 1990 AU COUNTY	red by O'Non				
the Leelanau Cou with a 3/4" i.d. box. Record witnesses 10" Cedar N65° 10" Cedar Sout 8" Cedar N87° 6" Cedar S70°	r Section 3 pted as a careful and inty Remonumentation galvanized iron pip 8: 8W 9.0' th 5.8' 9E 17.88' 9W 7.73'	faithful perpet Peer Review Grou e 3' long with a New witness 10" Cedar 10" Cedar 8" Cedar 6" Cedar	cuation of up, October brass capses: S65°W 7. S20°E 5. S89°E 17.	the origin r 23, 1996 p and proto .75' .50'	nal corner by				
		Date _	12/26/	196	CAND SUP				
Surveyor's Michigan License No.	35991	FORM A	PPROVED BY MICHGAN	STATE BOARD OF PROFE	SSIONAL SOME TORS JAN. 28, 1971				