

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: April 20, 2017

For corner(s) in: Houghton County

Original Public Land Survey Corner

Corner Code

a. S T 51N R 35W
 S T R
 S T R
 S T R

K5 (GCDB 600500)

Property Corner

1/16 Corner Code

b. S 12 T 51N R 35W
 S T R
 S T R
 S T R

L4 (GCDB 640540)

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Corner common to Sections 11-12-13-14. 1966 - Billy D. Buckler RLS remonumented the corner: "Squared and scribed 7" Elm at Section Corner. Placed corner at a fence corner, with fence running south and east. Streams both north and south check well. Corner lies at bottom of a steep bank facing south." Set 1" pipe with 4" alum. cap. 15" Cedar S16°W 36.6', 9" W.Spruce N35°E 11.2'.

b.) Center of Section 12. Found no record of prior monumentation.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1966 monument in good condition and at record bearing and distance from the Cedar 15" (now 22") S16°W 36.6', in good condition. Accepted the monument as the best available evidence of the position of the original corner.

b.) Established the position for the corner at the intersection of a straight line between the North and South 1/4 corners with the W'ly extension of an old fence line to the east, which forms a distinct line of occupation. The position falls in the center of Horoscope Road and is 26.4' south of a straight line between the East and West 1/4 corners.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Found 1" ID 1" pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
 7" B.Ash N84°E 28.85' mrkd "S12 NBT"
 7" B.Ash S56°E 13.85' "S13 NBT"
 22" Cedar S22°W 36.5' (1966 NBT) "S14 NBT"
 4" double Maple S87°W 21.2' "S11 NBT"
 Set wa'd cedar post adjacent.
 E= 7870289.88 N= 228043.42

b.) Set 5/8"x24" rebar with yellow plastic cap stamped "MICH D.N.R. PS 33986" 9" below the gravel road surface. Set measuring nail with MDNR tag in the side of:
 5" W.Pine N87°E 51.8' mrkd "C1/4 BT"
 13" R.Pine S21°E 83.2' do
 4" Spruce S33°W 61.2' do
 4" Poplar N32°W 66.75' do
 E= 7871109.82 N= 228854.91

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum
 Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Stephan J. Szyszkoski

07/20/2017

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

