

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 08/03/2016

For corner(s) in: Houghton County

Original Public Land Survey Corner

Corner Code

a. S T 51N R 36W
a. S T 52N R 36W
S T R
S T R

B1 (GCDB 140700)

B13 (GCDB 140100)

Property Corner

1/16 Corner Code

b. S 6 T 51N R 36W
S T R
S T R
S T R

11 (GCDB 120620)

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2		6		5		4		3		2		1		2
3														3
4		7		8		9		10		11		12		4
5														5
6		18		17		16		15		14		13		6
7														7
8		19		20		21		22		23		24		8
9														9
10		30		29		28		27		26		25		10
11														11
12		31		32		33		34		35		36		12
13														13
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A: Corner History

a.) Quarter corner common to Section 6 T51N-R36W and Section 31 T52N-R36W. 1963 - Billy D. Buckler RLS remonumented the corner, replacing a wood post set by W. Kuusisto 10/19/54. Noted on post B.T. was found. Set 1"ID Iron pipe with 4" aluminum cap. 10" Hard Maple N05°E 21.5 links, 10" Hard Maple S50°E 42 links. The monument was recovered and additional witnesses were made by Dennis Destrampe RLS #18983, date unknown: 11" Maple S55°W 45.49', 8" Maple S15°W 15.80', 5" Maple S78°E 18.36', 5" Maple S78°W 40.31'.

b.) Southwest 1/16 corner, Section 6. Not previously monumented.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1963 monument disturbed, having been knocked over by equipment or fallen tree. Restored the 1963 position at record bearing and distance from the stump remains of one of the 1963 NBTs and from two of the Destrampe witnesses, Sugar S78°E and Sugar S15°W, both in good condition and found with UPEA #18983 tags set with spikes in the sides of the trees. Reset the 1963 monument at this position.

b.) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

a.) Reset 1"IDx36" I.pipe with 4" MI Dept. of Conservation cap. Found measuring nail with tag in the side of:

9" Sugar S78°E 18.36' UPEA tag #18983

9" Sugar S15°W 15.80' do

Set measuring nail with MDNR tag in the side of:

3" Sugar S44°E 5.65' mrkd "1/4S NBT"

4" Sugar S83°W 47.2' do

Set sq'd cedar post adjacent.

E= 7853457.444 N= 231655.131

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters.

Coordinate Reference: NGS PID RL0593, E= 7868965.488 m. N= 221669.506 m.

(b.) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.

Set measuring nail with MDNR tag in the side of:

6" Sugar N70°E 11.95'

mrkd "1/16S BT"

9" Maple S28°E 5.9'

do

8" Sugar S63°W 23.65'

do

8" Sugar N74°W 18.35'

do

Set sq'd cedar post adjacent.

E= 7853023.321 N= 230484.495



Stephan J. Szyszkoski

09/07/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908