

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

# LAND CORNER RECORD

T. 51N N.R. 36W


Houghton COUNTY

DESCRIPTION OF CORNER Section corner common to Sections 25-26-35-36

CORNER MONUMENT 1" pipe with 4" aluminum cap.

DATE MONUMENT PLACED AND WITNESSED 9-12-62 with L. Stevens, D. F.

WITNESSES TO CORNER..... 9" Hard Maple (S36 NBT) S28°E, 31 links



9" Hard Maple (S35 NBT) S52°W, 43 links

6" Y. Birch (S25 NBT) N65°E, 28 links

AND

CIRCLE CORNER REGISTERED

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was re-established from a pine stub (probable line tree), 5.70 chs. north; a pine stump (probable line tree) 6.60 chains south; a stream 3.50 chains east and an original corner 1/2 mile west.  
Found down and rotted pine to north-east of corner for possible bearing tree.

SURVEYOR'S SEAL

SIGNED Billy D. Buckler DATE April 24, 1963  
REGISTERED LAND SURVEYOR  
Billy D. Buckler