

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T..51. NR..36..W

..H..o..u..g..h..t..o..n.. ..C..O..U..N..T..Y

DESCRIPTION OF CORNER ..Section corner common to Sections 5, 6, 7, and 8..

DESCRIPTION OF CORNER MONUMENT ..1" Pipe with 4" Brass Cap.. ..

WITNESSES TO CORNER ..12" Hard Maple .. (S 8 NBT) .. S 38° E .. 29 Links ..

14" Red Oak .. (S 5 NBT) .. N 40° E .. 30 Links ..

9" Hemlock .. (S 6 NBT) .. N 63° W .. 17 Links ..

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED. This corner was replaced at very old squared Hemlock tree (down).
No evidence of original witnesses. Distances east and west to 1/4 corners very
good.

Corner was placed and witnessed October 13, 1959 with Frank J. Bray.

SURVEYORS SEAL

SIGNED *Billy D. Buckler* DATE 2/26/60
REGISTERED LAND SURVEYOR
Billy D. Buckler