

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 36 T 52N R 35W	1
	S T R	(GCDB 620200)
	S 26 T 52N R 35W	9
3. Miscellaneous Property in Sec.	S T R	(GCDB 560240)
	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 9 10/13/14 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1-Sec. 36) West 1/16 corner between Sections 25 and 36. Not previously monumented.

(9-Sec. 26) Center-East 1/16 corner, Section 26. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-Sec. 36) Established the position for the corner midway and on the section line between Section  
corner 1346.87' west and Quarter corner 1346.87' east.

(9-Sec. 26) Established the position for the corner midway and on a straight line between Center of  
Section 26 1320.06' west and Quarter corner K10 1320.06' east.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
2" Maple in clump S21°E 11.9' mrkd " X X "  
2" Spruce S62°W 19.75' do  
6" Spruce S51°W 49.8' "1/16S BT"  
6" Spruce N55°W 34.5' do  
Set sq'd cedar post adjacent.  
E= 7870770.805 N= 232881.629

(9) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.  
Set measuring nail with MDNR tag in the side of:  
6" Sugar N02°E 5.25' mrkd "1/16S BT"  
6" Sugar N87°E 13.05' do  
14" Ash S08°E 2.0' do  
16" Hemlock S48°W 10.3' do  
Set sq'd cedar post adjacent.  
E= 7869992.356 N= 233644.714

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.  
Coord. Ref.=NGS PID RL0593: N= 221669.506 m. E= 7868965.488 m.

Signed by Stephan J. Szyszkoski Date 03/11/2015  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division