

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 52. NR. 35. W.

----- Houghton ----- COUNTY

DESCRIPTION OF CORNER 1/4 Corner between Sections 35 & 36 -----

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap -----

WITNESSES TO CORNER 12" Hemlock - S 84 W - 37 Links -----

12" Cedar - N 35 E - 20 Links -----

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was found by Forestry Division survey crew, while making a partial resurvey of this Township. Corner had been previously located by unknown Surveyor. Corner checks o.k. by measurement, North and South. One probable original R.T. still in place, badly rotted.

Corner was placed and witnessed September 23, 1953.

SURVEYORS SEAL

SIGNED James C. [Signature] DATE 1/15/54
REGISTERED LAND SURVEYOR