

✓

MICHIGAN
DEPARTMENT OF CONSERVATION
FORESTRY DIVISION

LAND CORNER RECORD

T. 52. NR. 35. W.

----- Houghton ----- COUNTY

DESCRIPTION OF CORNER Section Corner common to Sections 27, 28, 33, 34

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass cap

WITNESSES TO CORNER 36" Hemlock - S 74 E - 64 Links

12" E. Pine - N 72 W - 73 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR
RESTORED.

This corner was established, by double proportionate measurement, by
Forestry Division survey crew, while making a partial resurvey of this Township.
Corner placed 5 chains South of swamp edge, as per Government notes. One possible
original B.T. in place, poor condition.

Corner was placed and witnessed August 25, 1953.

SURVEYORS SEAL

SIGNED

John C. [Signature]
REGISTERED LAND SURVEYOR

DATE 1/15/54