

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Houghton</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T 52N R 36W	MC W. of K7
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 01/05/2012 do hereby state  
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2  
above were in conformance with regulations and rules therefore as required in the current manual of survey  
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of  
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with  
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,  
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(MC W. of K7) Meander corner West of Section corner K7 on the east side of Lake Gerald between  
Sections 14 and 23. 1846 - Established by S.W. Higgins and Hiram Higgins, Deputy Surveyors. West  
Corrected between Sec. 14 & 23...5.00 Set meander post on small lake. W.Pine 14" S35W 38 links,  
Cedar 8" N60W 15 links...13.00 Over arm of lake and set post...40.00 Set 1/4 Sec. post. Found no  
subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(MC W. of K7) Reestablished the position for the corner on the Section line between Sections 14 and  
23 at record distance of 5.00 chains (330') west of K7. The position for the corner falls in a small  
cove on the south side of Lake Gerald and cannot be monumented. Established a WITNESS CORNER 133.30'  
east of the record position, and 196.70' west of K7. The monument was placed in stable soil, on a  
line between K7 and a 3/4" iron pipe at the west side of the cove. The 3/4" pipe is located 726.89'  
west of Section corner K7 and I accept it as marking the location of the Section line.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(MC) Set 1"IDx32" I.pipe with 4" alum. MDNR cap  
set flush for a WITNESS CORNER to the MC 133.30'  
east of the record MC position.  
Set measuring nail with MDNR tag in the side of:  
12" Maple S20W 7.0' mrkd "WC BT"  
10" Maple N53W 4.05' do  
The NE corner of an electric service riser is  
S48W 31.4'  
A squared cedar post is 1 ft. South  
Bearings are magnetic.



Signed by Stephan J. Szyszkoski Date 01/26/2012  
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division