

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

SURVEY &  
REMONUMENTATION

SEP 17 1999

For corners in  
HOUGHTON  
(County)

Located In:

Corner Code #

SECTION

1. Public Land Survey  
13 T 53N R33W  
18 T 53N R32W  
T R  
T R  
T R  
2. Property Controlling  
in Section S T R  
S T R  
3. Miscellaneous  
Property in Section S T R  
S T R

M-6, M-7  
A-6, A-7  
Seg. 2

MARY SCHOOS 05/04/99  
HOUGHTON COUNTY, REGISTER 11:08  
LC 3/ 588 PAJ Fee: 9.00  
Page 1 of 1

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, R.W. CRAMPTON, in a field survey on DECEMBER 23, 19 97,  
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned  
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current  
manual of survey instructions of the United States Department of the Interior, Bureau of Land  
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and  
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a  
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found  
as expressed below:

**NOTE:** Not more than 4 corners, all in the same town and range, may be recorded  
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

A-6 & M-6, SET QUARTER POST MAPLE 6, N70E, 9, CEDAR 8, N41W, 4,  
N51W 20, Y. BIRCH TREE 10, S60W 14.

A-7 & M-7, FIR 6 CORNER OF SECTIONS 13 & 24, HEMLOCK 16, N29E, 28.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-6 & M-6, SQUARE HEADED BOLT, FOUND, WHICH AGREES WITH THE UNRECORDED PLAT OF PORTAGE  
VIEW LOTS.

A-7 & M-7, 3/4" IRON PIPE FOUND IN CENTERLINE OF COUNTY ROAD T-29 AND 4' EAST OF THE CENTERLINE  
OF COUNTY ROAD T-641 AND ON PROJECTION OF OLD FENCE, SOUTH OF CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-6 & M-6 SQUARE HEADED BOLT REPLACE WITH 1" IRON PIPE WITH 2 1/4" BRASS CAP. WITNESSED WITH  
SURVEY TAG NAILED TO: 17" HEMLOCK TREE S82°E 53.98', 5" W. BIRCH TREE S50°E 59.73',  
14" BALSAM TREE S77°W 36.54', 24" SPRUCE TREE N19°W 46.64'.

A-7 & M-7 3/4" IRON PIPE REPLACED WITH 1" IRON PIPE WITH 2 1/4" BRASS CAP WITNESSED WITH SURVEY  
TAG NAILED TO: UTILITY POLE N60°W 43.14', UTILITY POLE S60°W 42.04',  
12" BALSAM TREE SOUTH 65.87', 6" SPRUCE TREE S70°E 110.77'.



Signed by Robert W. Crampton

Date MARCH 22, 1999

Surveyor's Michigan License No. 24591