

✓

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T. 53 NR 34-35 W.

Houghton

COUNTY

DESCRIPTION OF CORNER Section corner common to Sec.'s 30-31-25-36

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 7" Cedar N 58° W 25 links  
"S 25° EBT"

9" Cedar N 79° E 34 links  
"S 30° EBT"

8" Cedar S 1° E 8 links  
"EBT"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED.

Replaced section corner from one cedar B.T. bearing S 35° W 8 links.  
Tree cut down and in poor condition. Found cedar stump S 35° E 12 links.  
Found cedar post in proper position. Corner lies in swamp.

Found by Forestry Division Survey Crew.

SURVEYORS SEAL

SIGNED Billy D. Buckles DATE 8/28/57  
REGISTERED LAND SURVEYOR