

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Houghton Located In: Corner Code #
1. Public Land Survey T 53N R 35W I13
2. Property Controlling in Section S T R
3. Miscellaneous Property in Sec. S T R
4. Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

Table with 13 rows and 13 columns (A-M) for Register of Deeds Stamp & File Number.

I, Stephan J. Szyszkoski, in a field survey on 10/05/15 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(I13) Standard Section corner to Sections 34 and 35, T53N-R35W. Not a common corner with Sections 2 and 3, T52N-R35W. 1845 - W.A.Burt, Deputy, set post. Birch 14" N09°E 16 links, Fir 8" N14°W 28 links. 1944 - William A. Waara "found 4" sq. ced.stke. in level ced. swamp. Found 22" bir. B.T. with P.A.L. mark N14°E 12 ft. Found 14" sq. off spruce N46°W 5 ft. Found 20" r. map. B.T. S50°W 20 ft. Put Y. tag on 4" r. map. S62°W 6 ft. Put names and W.A.W. mark on 6" hem. S28°E 6 ft." 1846 - S.W. Higgins, Deputy, running between Sections 2 and 3, T52N-R35W, intersected the Township line 30 links west of the Standard corner and set post. Maple 9" S48°E 16 links, Spruce 12" S48°W 32 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(I13) Did not find the cedar stake noted in 1944. Remonumented the corner at record bearing and distance from the Y.Birch B.T. 14" N09°E 16 links, now a rotted stump with no marks visible, approx. 24" dia., and at record bearing and distance from the two W.A.W. NBTs - Maple S62°W 6 ft. (no tag found), and Hemlock S28°E 6 ft. Both of the 1944 witnesses are in good condition with overgrown blazes. Also found the 14" sq. off spruce N46°W 5 feet noted in 1944, now a rotted stump mound at record bearing and distance. I note that the Closing Corner B.T. Maple S48°E 16 links is in place, living, with rotted face. Found traces of the measuring notch facing NW, toward the position of the C.C., which was not remonumented this date.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I13) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 5" Hemlock N37°W 10.35' mrkd "S34 NBT" 12" Maple N59°E 8.1' "S35 NBT" 14" Hemlock S24°E 6.25' mrkd "S2 NBT" (1944 NBT) 10" Maple S54°W 6.6' do do Set sq'd cedar post adjacent. E= 7868947.064 N= 240985.787



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum. Coord. Ref.=NGS PID D08499: N= 221257.624 m. E= 7884435.169 m.

Signed by [Signature] Date 11/04/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division