

APRIL 30, 1999
Robert W. Carver

SEP 17 1999

SECTION

Houghton
(County)

Corner Code #

- T 54N R 33W
T 54N R 33W TL
T R
T R
T R
T R
T R
T R
- I-13
I-12
Seg #2

MARY SCHOOS 05/19/99 2
HOUGHTON COUNTY, REGISTER 13:53
LC 3/ 600 PAU Fee: 9.00
Page 1 of 1

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Figure 1 is a 13x13 grid with columns labeled A through M and rows labeled 1 through 13. The grid contains 36 numbered points. Points 1 through 12 are located at (A,1), (B,1), (D,1), (F,1), (H,1), (J,1), (L,1), (A,2), (B,2), (D,2), (F,2), (H,2), (J,2), (L,2), (A,3), (B,3), (D,3), (F,3), (H,3), (J,3), (L,3), (A,4), (B,4), (D,4), (F,4), (H,4), (J,4), (L,4), (A,5), (B,5), (D,5), (F,5), (H,5), (J,5), (L,5), (A,6), (B,6), (D,6), (F,6), (H,6), (J,6), (L,6), (A,7), (B,7), (D,7), (F,7), (H,7), (J,7), (L,7), (A,8), (B,8), (D,8), (F,8), (H,8), (J,8), (L,8), (A,9), (B,9), (D,9), (F,9), (H,9), (J,9), (L,9), (A,10), (B,10), (D,10), (F,10), (H,10), (J,10), (L,10), (A,11), (B,11), (D,11), (F,11), (H,11), (J,11), (L,11), (A,12), (B,12), (D,12), (F,12), (H,12), (J,12), (L,12), (A,13), (B,13), (D,13), (F,13), (H,13), (J,13), (L,13). Points 13 through 36 are located at (B,1), (D,1), (F,1), (H,1), (J,1), (L,1), (B,2), (D,2), (F,2), (H,2), (J,2), (L,2), (B,3), (D,3), (F,3), (H,3), (J,3), (L,3), (B,4), (D,4), (F,4), (H,4), (J,4), (L,4), (B,5), (D,5), (F,5), (H,5), (J,5), (L,5), (B,6), (D,6), (F,6), (H,6), (J,6), (L,6), (B,7), (D,7), (F,7), (H,7), (J,7), (L,7), (B,8), (D,8), (F,8), (H,8), (J,8), (L,8), (B,9), (D,9), (F,9), (H,9), (J,9), (L,9), (B,10), (D,10), (F,10), (H,10), (J,10), (L,10), (B,11), (D,11), (F,11), (H,11), (J,11), (L,11), (B,12), (D,12), (F,12), (H,12), (J,12), (L,12), (B,13), (D,13), (F,13), (H,13), (J,13), (L,13). Points 34 and 35 are marked with solid black circles.

A. Description of original monument and accessories and/or subsequent restoration:

1-12 Wood Post - 1845 by D. Houghton.

Yellow Birch, 8", S38°W, 7 LKS

I-13 Wood Post

Fir, 8", N35°W, 33 LKS

Yellow Birch, 10", N13°E, 13 LKS

Per Land Corner Recordation Certificate by John I. Haataja: Vol. 1, Page 161

According to local resident an iron pipe in center of road was marking this corner at one time.

Nail in road established by John I. Haattaja.

No original evidence found.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1-12 Found 1½" I.D. Pipe. Accepted corner as found.

I-13 Found 1½" square pin centerline intersection of 2 track and Co. Rd. T-641.

Found Brass Tag #19833 and nail in utility pole N64°E 63.80'. Accepted corner as found.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(I-12) Set 2" Brass remon cap on top of found pipe. Set witness with 60d nail, brass "UPEA" tag, chest blaze.

Sugar Maple, 10", SCR, NBT, N14°E, 6.30'

Red Maple, 10", SCR. NBT, S51°E, 26.31'

Sugar Maple, 8", SCR. NBT, N36°W, 26.35'

Sugar Maple, 12", SCR NBT, S86°W, 8.31'

(I-13) Set 2" Brass remon cap on top of found square pin. Set witness with 60d nail, brass "UPEA" tag, chest blaze.

Oak, 9", SCR NBT, N33°W, 59.85'

Oak, 6", SCR NBT, S33°W, 35.94'

White Birch, SCR NBT, S44°E, 48.61'

Signed by PAV

Surveyor's Michigan License No. 43053

Date 5-8-45 SHROBEN

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 No. 4305

REVISÉ JAN., 1983
REVISÉ OCT., 1995