

SURVEY & REMONUMENTATION

SEP 17 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Houghton
(County)

Located in: 35

Corner Code #

SECTION

1. Public Land Survey

T 54N R 33W 16 J-13

T R

T R 0

T R *Sec. #2*

T R 0

2. Property Controlling in Section

S T R 0

3. Miscellaneous

S T R

MARY SCHDOOS 05/19/99 2

HOUGHTON COUNTY, REGISTER 13:56

LC 3/ 613 PAU Fee: 9.00

Page 1 of 1

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims

I, Robert A. Goodreau in a field survey on September, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

J-13 Post Set - 1845 by D. Houghton

Cedar, 12", N65°E, 40 LKS

Fir, 10", N12°W, 31 LKS

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

J-13 Nothing found. Corner was set by using single proportion method between southwest corner Section 35 and southeast corner Section 35.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
J-13 Set 1" galvanized pipe, 2" brass remon cap in approx. centerline of Co. Rd. T-1641. Witness set with 60d nail, brass
"UPEA" tags, chest blaze.

Hemlock, 7", SCR. NBT N24°W, 58.19'

Balsum Fir, 9", SCR. NBT, N31°E, 51.46'

Balsum Fir, 8", SCR. NBT, S33°E, 37.70'

Balsum Fir, 11", SCR. NBT, S28°W, 33.25'

Signed by

Date _____

Surveyor's Michigan License No. 43053



FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975

REVISED JAN., 198
REVISED OCT., 199