

Ronald W. Haataja
Oct 28, 1999

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

JAN 25 2000

For corners in

Houghton
(County)

Located in:

Corner Code #

SECTION

1. Public Land Survey T 55N R 34W H-7
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Section S _____ T _____ R _____

Mary Schoos
Register of Deeds
Houghton County, Register
Page 1 of 1 LC 4/67
PAU Date 12/30/1999 Time 10:54:48
EEF.

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Ronald S. Haataja, in a field survey on October 12, 19 99,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current
manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found
as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(H-7) North Quarter corner Section 22, T55N-R34W
40.30 Set Quarter Section Post
References: Yellow Birch 10" S12°W 13 lks.
Sugar 8" N33°E 32 lks.

	A	B	C	D	E	F	G	H	I	J	K	L
2	6		5		4		3		2		1	
3												
4	7		6		8		10		11		12	
5												
6	18		17		16		15		14		13	
7												
8	19		20		21		22		23		24	
9												
10	30		29		28		27		26		25	
11												
12	31		32		33		34		35		36	
13												



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(H-7) North Quarter corner Section 22, T55N-R34W
No evidence of original corner or accessories found.
Set 1-1/2" Iron Pipe at the midpoint and on line between
the Northeast and the Northwest corners of Section 22,
T55N-R34W

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(H-7) North Quarter corner Section 22, T55N-R34W
1-1/2" Iron Pipe. Cemented on a brass Houghton County
Remonumentation cap.
Witnesses: Brass Tags PS#39478 nailed into side of trees.
8" Ash N12°E 3.78'
5" Ash S61°E 19.47'
10" Aspen S07°E 15.25'
4" Sugar Plum N69°W 22.64'

Signed by Ronald S. Haataja

Date October 20, 1999

Surveyor's Michigan License No. 39478