

2000 REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For Corners in

Huron
(County)

Located in:

Corner Code #

STATE OF MICHIGAN
HURON COUNTY
RECORDED

29 NOV 2000 11:22 AM

FRANCES L. HOLDWICK
REGISTER OF DEEDS

1. Public Land survey: Brookfield T 15_N R 10_E

T R

T R

T R

T R

T R

T R

T R

T R

A-11

A-12

A-12

A-12

A-12

A-12

A-12

A-12

A-12

2. Property Controlling

S

T

R

in Section

S

T

R

3. Miscellaneous

S

T

R

Property in Sec.

S

T

R

JAN 19 2001

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

SECTION

5. Private Claims

I, James T. Meek, in a field survey on October 1, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules thereof as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expessed below:

	A	B	C	D	E	F	G	H	I	J	K	L
2	8	5	4	3	2	1						
3												
4	7	8	9	10	11	12						
5												
6	18	17	16	15	14	13						
7												
8	19	20	21	22	23	24						
9												
10	30	29	28	27	26	25						
11												
12	31	32	33	34	35	36						
13												

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original survey, West Bdy. T15NR10E, 1835, Harvey Parke D.S.

A-11 Corner of Sections 30, 31

Post

Elm 12", N20°W, 27½ links

Cedar 6", S18°W, 9 links

County Surveyor's Record: pin in a post

Recorded Surveys: none

LCRC: none

A-12 West ¼ Corner of Section 31

Post

B. Ash 16", S37°W, 13½ links

Maple 7", N33°W, 35 links

County Surveyor's Record: none

Recorded Surveys: none

LCRC: none

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11 Corner of Sections 30, 31

Found 1" iron in mon box

At intersection Bay Port & Bach Roads

Accepted as the best available evidence of the original corner position.

A-12 West ¼ Corner of Section 31

Found 2" iron in mon box

3' East of centerline of Bay Port Road

Occupation bears West

Accepted as the best available evidence of the original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 Corner of Sections 30, 31

1" iron in mon box

From which:

Road sign post bears N75°E, 34.6'

Wood sign post bears S15°E, 51.8'

Tag in power pole bears S30°W, 76.6'

Tag in power pole bears N10°W, 128.6'

A-12, ¼ Corner of Section 31 bears

S0°00'02"E, 2631.78'

A-10, ¼ Corner of Section 30 bears

N0°19'59"W, 2631.60'

A-12 West ¼ Corner of Section 31

2" iron in mon box

From which:

½" iron bears N45°E, 20.0'

½" iron bears S45°E, 20.0'

½" iron bears S45°W, 30.0'

½" iron bears N45°W, 30.0'

A-13, Corner of T14-15N, R9-10E bears

S0°00'00"E, 2631.74'

A-11, Corner of Sections 30,31 bears

N0°00'02"W, 2631.78'

Signed by

Date

Surveyor's Michigan License No. 39089

APPROVED AT PEER BOARD MEETING 11-02-00 RAB

