

SURVEY &  
REMONUMENTATION

JAN 22 1998

Re-Mon Liber 1 Page 135

SECTION

1997 REMONUMENTATION  
LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COLFAX TOWNSHIP

HURON

(County)

Located In:

Corner Code #

1. Public Land Survey

T16N R12E K-13

T R

T R

T R

T R

T R

T R

T R

T R

2. Property Controlling  
in Section

S

S

S

S

3. Miscellaneous  
Property in Sec.

S

S

S

S

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN  
HURON COUNTY  
RECORDED

12 DEC 97 12:40 P.M.

FRANCES L. HOLDWICK  
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, Russell L. Brown, in a field survey on Nov. 24, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1834 G.L.O. H. Parke D.S. Set Post Corner Sections 35 and 36

B. Ash 16 N87E 27 1/2 B. Ash 11 N66 1/2W 54

COUNTY SURVEYORS RECORDS: None

COUNTY ROAD COMMISSION RECORDS: None

ACT 74 FORM: None

RECORDED SURVEYS: None

County Drain Commission Minutes of Survey for the relocated Van Hevel & Branch #1 Drain. Drain Notes State drain crosses South line of Section 36, 33 feet East of the Southwest Corner of Section 36.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original corner or accessories found.

Set 1/2" x 18" Steel Stake by single proportionate measurement between M-13 (Southeast Corner Section 36, T16N-R12E) and I-13 (Corner Sections 34 and 35, T16N-R12E) as best evidence of original corner position.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-13 Corner Sections 35 and 36, T16N-R12E

Set 1/2" x 18" Steel Stake Capped 24588

WITNESSES:

N25°W 50.85' to P.K. Nail in W. Side Wood Post

N60°E 75.91' to P.K. Nail in N.W. Side P.P.

S40°E 51.97' to 1/2" x 18" Re-Rod

S70°W 47.93' to 1/2" x 18" Re-Rod

East 31.50' to Approximate Centerline of relocated Van Hevel Drain

East 13.14' to 5/8" Steel Stake Centerline of Barrie Road and Popple Road,

Apparent Corner Section 1 and 2, T15N-R12E

East 2634.63' to South 1/4 Corner Section 36, T16N-R12E, L-13

West 2634.62' to South 1/4 Corner Section 35, T16N-R12E, J-13

Signed by Russell L. Brown Date December 9, 1997

Surveyor's Michigan License No. 24588

PEER GROUP APPROVED

AT MEETING HELD

DEC. 11, 1997.

RLB

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

REVISED OCT., 1995

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

