



LIBER 3 PAGE 225  
REMONUMENTATION

128726 RECORDED  
HILLSDALE CO. MICH.

LAND CORNER RECORDATION CERTIFICATE '97 NOV 26 PM 4 07  
Filing Requirement of Act 74, Mich. P.A. 1970

Jeffrey A. Bieszk  
REG. OF DEEDS  
SURVEY &  
REMONUMENTATION

FEB 11 1998

SECTION  
Register of Deeds Stamp & File Number

For corners in

HILLSDALE  
(County)

Located In:

Corner Code #

- |                                    |           |     |
|------------------------------------|-----------|-----|
| 1. Public Land Survey              | T 6S R 1W | G-4 |
|                                    | T R       |     |
|                                    | T R       |     |
|                                    | T R       |     |
|                                    | T R       |     |
| 2. Property Controlling in Section | S T R     |     |
|                                    | S T R     |     |
| 3. Miscellaneous                   | S T R     |     |
| Property in Sec.                   | S T R     |     |

4. Lot No. , Recorded Plat

5. Private Claims

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

I, Jeffrey A. Bieszk, in a field survey on 12 November, 19 97, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Robert Clark Jr. (1824)  
6" Ironwood N 12 E 28 lks  
5" Ironwood S 14 W 24 lks

County Survey (George Marks 1901)  
Found Stone  
no witnesses taken  
40.04 1/8 Chains North of G-5

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found no iron, dug at a location from proportional measurement from George Marks survey, found stone as the same distance from George Marks survey. Accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box		
Nail w/tag 14" Walnut	S 80 W	39.00 ft.
Nail w/tag 20" Twin Box Elder	N 25 E	57.05 ft.
Nail w/tag fence post	S 85 E	31.60 ft.
Nail w/tag 22" Maple	S 65 E	39.24 ft.



Signed by Jeffrey A. Bieszk Date 25 November 1997

Surveyor's Michigan License No. 41093