



LIBER 3 PAGE 301

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

12403

RECORDED
HILLSDALE CO. MICH.

'98 DEC 4 AM 11 47

For corners in

HILLSDALE
(County)

Located In:

Corner Code #

- | | | | |
|------------------------------------|-------------|-------------------------|------------|
| 1. Public Land Survey | | T <u>7S</u> R <u>1W</u> | <u>C-6</u> |
| | | T <u> </u> R <u> </u> | <u> </u> |
| | | T <u> </u> R <u> </u> | <u> </u> |
| | | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling in Section | S <u> </u> | T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> | T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous Property in Sec. | S <u> </u> | T <u> </u> R <u> </u> | <u> </u> |
| | S <u> </u> | T <u> </u> R <u> </u> | <u> </u> |

Jeffrey A. Bieszk
REG. OF DEEDS
SURVEY &
REMONUMENTATION
FEB 23 1999
SECTION
Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Jeffrey A. Bieszk, in a field survey on 25 Nov, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO
Post
9" Beech N6E 21 lks
12" Beech S62W 9 lks

LCRC L1 P497 Alan Ringenburg
R.R. Spike
14" Triple Cherry S78E 44.03 ft.
18" Maple N69W 102.92 ft.
24" Tree N11W 109.63 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R. Spike as witnessed by Ringenburg, who set R.R. spike by extending W1/4 Corner Section 17 through Found C1/4 Corner and intersect the East Line of Section 17. Dug and found nothing but it did fit occupation around it. Accepted as the best available evidence to the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box
Nail & Tag Twin Cherry S 87 E 43.43 ft.
Nail and Tag Power Pole N 75 E 40.71 ft.
Nail and Tag Power Pole S 75 W 68.77 ft.
Nail & Tag 48" Oak N 15 W 107.98 ft.



Signed by *Jeffrey A. Bieszk*
Surveyor's Michigan License No. 41093

Date 4 Decem Ber 1998