00 NOV 17 PH 3:41

ACCEPTED BY THE HILLSDALE COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER MICHIGAN PUBLIC ACT 345 OF 1989 AT A MEETING HELD ON AL RIMGENBERG, CO. REP.

For corners in

LIBER 5 PAGE 55

HILLSDALE COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

her Danganer

HILLSDALE COUNTY READING TWP (County)	Located In:	Corner Code #		SURVEY & .5MONUMENTATION												
1. Public Land Survey	T_7 S_R_4 WB-5 T R T R				JAN 1 2 2001 SECTION											
2. Property Controlling S	T R T R T R T R			Re						mp 8	š Fii	le N	umb	er		
4. Lot No, Recorded Pl	at			A	ВО	- D	E	F	G	н	I	J	к	T, N		
5. Private Claims				_	6	5	-	4	+	_3- 	-	- <u>2</u> -		1—		
			3		7	[3—	 	-	-10-	\bot	-11-		12-		
I, <u>EDWARD W. REED</u> , in a field survey on <u>NOVEMBER 1</u> , 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented,				_	18—	-1	7	—16		15	+	14		13-		
					19—	_2	<u>-</u>	21	_	22-		-23-	:	24—		
recovered, found as expressed below:			10] 30	2	9	2E	-	27-	_	 26-	-	 25		
NOTE: Not more than 2 comers, all in a on this certificate.	the same town and range,	may be recorded	11 12 13	-	31—	3:	2	33		34 34		_35_ 		36		

QUARTER CORNER COMMON TO SECTIONS 7 & 18, READING TOWNSHIP, HILLSDALE COUNTY, MICHIGAN

A. Description of original monument and accessories and/or subsequent restoration:

GLO CORNER SET

1867: MARKS, SURVEYOR-STONE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

DUG TO DEPTH OF 4' ENTIRE WIDTH OF ROAD CORNER NOW GONE DUE TO BOAD GRADING PRACTICES RESET CORNER USING GLO DISTANCES AND EXISTING FENCELINES FROM SURVEY OF MARKS SET 3/4" X 30" REBAR IRON WITH REMON CAP IN CAST IRON BOX 4" BELOW GRAVEL ROAD SURFACE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET 3/4" X 30" REBAR IRON WITH REMON CAP IN CAST IRON BOX 4" BELOW GRAVEL ROAD SURFACE

IN LINE WITH FENCELINE RUNNING SOUTH

2' ROUND CONCRETE POST

36" MAPLE

8" WALNUT

6" MAPLE

6" OAK

N5E 27.3' N60E 59.8' S5E 15.9'

N42W 29.5'

S40E 59.8'

AND IS ACCEPTED AS A CAREFUL AND FAITHFUL REESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER.

Signed by _____ Calmu W \ ay

EÓWARD R. REED

Surveyor's Michigan License No. 33985

