034009

LIBER 5 PAGE 6

RECORDED HULLSGALE CO. MICH.

LSDALE COUNTY REMONUMENTATION PROGRAM LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

GO SEP 14 AHII: 36

July Conformer

<u> </u>	111
SURVEY PEER GROUP AS THE OFFICIAL	
CORNER UNDER MICHIGAN PUBLIC ACT 345	
OF 1990 AT A MEETING MELD ON	
1-7-13-00 All 0 > 1	
War - 1	١.
AL RINGENBERG, CO. REP.	1
Y	1

For corners in HILLSDALE COUNTY Located In: Corner Code # SURVEY & READING TWP EMONUMENTATION T<u>7S</u> R<u>4W</u> 1. Public Land Survey JAN 1 2 2001 ____ R___ R R SECTION 2. Property Controlling Register of Deeds Stamp & File Number in Section 3. Miscellaneous Property in Sec. 4. Lot No. _____, Recorded Plat ____ 5. Private Claims I, <u>EDWARD W. REED</u>, in a field survey on <u>AUGUST 17</u>, 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 6

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found

QUARTER CORNER COMMON TO SECTIONS 12 AND 13

A. Description of original monument and accessories and/or subsequent restoration:

1825: WM BROOKFIELD - CORNER SET

as expressed below:

1877: GEO MARKS - STAKE (WITNESS NORTHWEST CORNER DWELLING S41°E 181 LINKS)

1973: A.J. HATT - SET RAILROAD SPIKE IN LINE WITH FENCE TO THE NORTH AND WITH WITNESSES OF MARKS, RECORDED IN LCRC # 4876, LIBER 1, PAGE 347

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND RAILROAD SPIKE FITTING WITNESSES OF HATT AND MARKS FOUND RAILROAD SPIKE OF BURRIS S45°W 4.05' FROM HATTS IRON NOTHING FOUND BELOW HATTS IRON, ACCEPTED HATT'S IRON AS BEST EVIDENCE SET 3/4" x 30" IRON WITH REMON CAP IN CAST IRON BOX FLUSH WITH PAVED ROAD

C.	Description of	monument for	corner and	accessories	established	to nemetuate	locating the	e nosition i	of the o	corner
٠.	DOSSI PLISTI OF	THORIGING ICE	COLLIGI GIIG	accessories	COLGUNIONICU	in neinernare	iocausiu uii	ซมบอเนบทา	31 LHC 1	SOLLIGE.

	9 03 (40)131	ica to poil
TOP CENTER OF TELEPHONE PEDESTAL	N7°E	25.00'
NORTHWEST CORNER OF FARMHOUSE	S41°E	119.46'
PK NAIL SW SIDE 18" WALNUT	N55°W	39.05
RAILROAD SPIKE BY BURRIS	S54°W	4.05'
PK NAIL WEST SIDE OF POWER POLE	S7°E	32.781
PINE TREE	S26°E	64.351
CENTERLINE OF ROAD	SOUTH	3.85'

EDWARD W. REED LAND SURVEYOR NO. 33995 D LAND SURVE

AND IS ACCEPTED AS THE BEST AVAILABLE EVIDENCE OF THE POSITION OF THE ORIGINAL CORNER.

Signed by all Whi

DATED: AUGUST 17, 2000

EDWARD W. REED

Surveyor's Michigan License No. 33985