



LIBER 5 PAGE 18

034936

RECORDED
HILLSDALE CO. MICH.

00 OCT 11 AM 10:30

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

- | | | |
|-------------------------|-------------------------------------------|-------------|
| 1. Public Land Survey | T <u>8S</u> R <u>1W</u> | <u>A-11</u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| | T <u> </u> R <u> </u> | <u> </u> |
| 2. Property Controlling | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| in Section | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| 3. Miscellaneous | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |
| Property in Sec. | S <u> </u> T <u> </u> R <u> </u> | <u> </u> |

SURVEY &
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824)	Geo. Mark (1867) survey #454	LCRC Donald Olmstead L1-P506
8" W. Ash N80E 43 lks.	Stake	Set iron
10" Beech S20E 43 lks.	14" Beech S20E 43 lks	Phone box NW 87.73 ft.
92 lks South M-11 T8S-R2W	15" Elm South 7.5 lks	Tri Conc. Post SE 49.05 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron as in Donald Olmstead LCRC and as was in his survey in Liber 1 of Surveys page 461. In Olmstead's survey he shows that the corner was 60.52 feet South of M-11 T8S-R2W, the GLO has it as 60.72 feet. Olmstead set the corner by double proportional measurement. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box		
West Leg Stop Sign	S 80 E	18.62 ft.
Weight Limit Sign	N 45W	94.02 ft.
Weight Limit Sign	N 05 E	127.48 ft.
Road Sign	N 85 E	97.51 ft.



Signed by [Signature]
Surveyor's Michigan License No. 41093

Date October 11, 2000