



LIBER 5 PAGE 19

034937

RECORDED
HILLSDALE CO MICH.

00 OCT 11 AM 10:30

REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

Located In:

Corner Code #

1. Public Land Survey

T	8S	R	1W	B-11
T		R		
T		R		
T		R		
T		R		

2. Property Controlling
in Section

S	T	R		
S	T	R		

3. Miscellaneous
Property in Sec.

S	T	R		
S	T	R		

SURVEY &
EMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000, do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824)
22" Maple N6E 19 lks
18" Hickory S63W 28 lks.

Geo. Mark (1867) survey #454
Stake
20" Locust S61 ¾ E 64 lks.

Geo. Mark (1883) survey #961
Stone
Stone South 50 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found R.R spike in line with fence to the South, R.R. spike was in the same line as A-11 and C-11. Dug under R.R. spike and found nothing, looked for Stone to the South found nothing. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box

Nail w/tag in Power Pole	S 40 W	91.28 ft.
Nail w/tag 16" Maple	S 05 W	58.57 ft.
Nail w/tag 30" Ash	S 15 E	60.39 ft.
Nail w/tag 12" Beech	N 70 E	79.92 ft.

Signed by [signature]
Surveyor's Michigan License No. 41093Date October 11, 2000