

ACCEPTED BY THE HILLSDALE
SURVEY PEER GROUP AS THE
CORNER UNDER MICHIGAN PUBLIC ACT
OF 1890 AT A MEETING HELD
ON 10-11-00
AL RINGENBERG

LIBER 5 PAGE 27
REMONUMENTATION

034945

RECORDED
HILLSDALE CO. MICH.
00 OCT 11 AM 10:31

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

HILLSDALE

(County)

Located in:

Corner Code #

1. Public Land Survey T 8S R 1W J-11
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

SURVEY &
REMONUMENTATION

JAN 12 2001

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

I, Jeffrey A. Bieszk, in a field survey on 6 Oct. 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

GLO set by Ziba Swan (1824)
8" Beech S87E 32 lks
11" Beech N39W 27 lks.

Larry M. Gerschbacher LCRC L555 P441
Set 5/8" x 24" Rebar
10" Twin Box Elder N18W 30.21 ft.
18" Box Elder S76W 71.41 ft.
20" Box Elder S05E 25.70 ft.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron as witnessed by Gerschbacher. The iron was 2 feet South centerline of Road in line fences North and South. He set corner at spilt of occupational evidence (fence corners). Dug and found nothing else. Accepted as the best available evidence of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 5/8" x 36" iron w/cap in Monument Box
Nail w/tag 36" Box Elder N 15 W 30.51 ft.
Nail w/tag 24" Box Elder S 05 E 25.52 ft.
Nail w/tag 42" Box Elder S 50 W 70.76 ft.
NE Corner Pole Barn S 10 W 92.60 ft.



Signed by [Signature]
Surveyor's Michigan License No. 41093

Date October 11, 2000