LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1976 PAGE 203

For corners in IONIA (County)	Located In:	Corner Code #			10	OF MI	YTYU	าก	
1. Public Land Survey	T_8N_R_6W TR TR	K-11				VED F01		-	
Property Controlling S in Section S Miscellaneous S Property in Sec. S	T R T R	Re	giste	er of D	REGI	NE M. I STER OI Stamp	F DEEDS	;	r
4. Lot No, Rec 5. Private Claims	corded Plat		1 2		T	E F			L
I, MARINUS MULDER	3 4	7	8	9	10	11	1:		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					17	16	15	14	1:
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:				19	20	21	22	23	24
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.					29	28	27	26	28
This corner was firm	st set by U.S. Deput	and/or subsequent restoration: Ty Surveyor, Orange Risdon	12 13		32	33	34	35	36
W 32 links. Perpetuation: D.C. section 25, July 18: Crawford showed 2 with Apple N 73° W 40 line A note in the marginathe G.L.O. notes recorner." This note Road Commission has stone" 40" Elm N.E. West 30.9 feet. Pro	Crawford former Ion 88 recorded in Volum itnesses to the corn aks and 10" Apple Son next to the inform ads: "This corner found on page 287 wwitnesses for K-11 31.83 feet; 12" Oak ofessional Surveyor	tia County Surveyor perform te 1, page 440 of the Ionia ter but did not say what wa 48° W 59 1/2 links. ation for K-11 found in the found in 1911. Raised up to was in D.C. Crawford's hand in its county index maps. S.E. 65.15 feet; 18" Elm Richard Crater No. 16924 r boat spike and stone.	ed Co s s e C o n l wr It S.W	a secunty et. ' ounty ew ro iting stat	stion Surv The w Surv Surv Surv Surv Surv Surv Surv Surv	reyors reyors reyor red. The Ic "Boo	rvey s recesses a cs cop Good onia (at sp:	in ords. are: py of ston Count ike a	6' ie :Y ind
B. Description of corner e	evidence found and/or metho	od applied in restoring or reestablishing	g cor	ner:					

Found 2 boat spikes over large stone with stones around the base 17" below the gravel road surface 3 feet more or less West of the centerline of Westbrook Road and approximately on the centerline of Schaefer Road to the East and remains of a tree and fence line to the West. Accepted the stone as the correct corner. One of the County Road Commission witness trees still remains, being the 12" Oak Southeast.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set 3/4" x 24" steel rod with a 2 3/4" diameter cap stamped "Ionia County P.S. 25863" on the South side of the stone, witnessed by:

Nail & tag West side 26" Oak S 22° E 63.77 feet

Nail' & tag South side 8" Elm S 85° W 41.07 feet

Nail & tag Southwest side 4" wood post N 36° W 44.96 feet

Nail & tag Southeast side 22" Oak N 70° E 46.77 feet

Ratified by Peer Group P.A. 345 Ionia County

Date 9-27-95 Matinus A. Maluar, Chairman

Signed by Maril a. mulli	Date	OCTOBER 2, 1995	
Surveyor's Michigan License No. 25863		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28	3. 197