## SURVEY & . REMONUMENTATION

APR 2 7 1995

For corners in

in Section

3. Miscellaneous

5. Private Claims \_

Property in Sec.

## COMMISSION

IOSCO COUNTY REMONUMENTATION CORNER LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN IOSCO COUNTY FILED

T.osco (County)	Located In:	Corner Code ##
. Public Land Survey	T 22N R 8E	(C-9 to C-10
•	T R T R	
. Property Controlling S	т	No. 3

S \_\_\_\_ R \_\_\_

\_ , Recorded Plat \_

5 DEC 94 1:53 P.M.

BONITA N. COYLE REGISTER OF DEEDS

94-21

Register of Deeds Stamp & File Number

	0.4
James H. Granger , in a field survey on _ September	94
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points	
in lines 1 and 2 above were in conformance with regulations and rules therefore as req	uired in the
current manual of survey instructions of the United States Department of the Interior, Bur	
Management or by a decree of a Court of Law and/or that the corner points mentioned in line	es 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a	
Court of Law; established, re-established, monumented; re-monumented, recovered	, found as

expressed below NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

-	A	8	С	D	E	F	G	Н	1 J	K	L	M
2		6		5		 4 —		3				
3	<u> </u>		<u> </u>	<u> </u>	<u> </u>		<u> </u>				_	
4	_	ļ_	L	 B—		 9	L	 10	_ <sub> </sub>	1		2
5		1_	L			_	╙	<u> </u>	Ш		_	
6	_	 18	L	 17	L,	  6	$\perp$	 15	L,	4	1	3
7	L	Ĺ				Ĺ		Ĺ	أسا			_
8		 19	ļ_;	 20—	L.	 !1—	L	22	2	3—	2	4
9	_	_		<u> </u>		_	<u> </u>					
10	L:	 30—	<b>\$</b> _:	 29—	_2	8	<u> </u> _;	 27——	[	6	—2	5
11	L	<u> </u>	L	_	ļ	<u> </u>	╙	_	Ш			
12	<u> </u> .	 31—	Ļ;	2	<u> </u>	 33—	<u> </u> _,	 34	3	5—	3	6
13	1	1 .		l		1			lΙ		ļ	

A. Description of original monument and accessories and/or subsequent restoration:

1843 Original Survey

Set Wood Post

12" Yellow-Pine N78°W 41 lks

John Mullett

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Field search located cor. C-9 and monuments on sec. line as shown on MDOT road plans. Extended sec. line south and meander cor. falls 70' into Lake Huron.

Set witness cor. 138.06' N. of cor. position on section line.

ACCEPTED BY THE IOSCO COUNTY SURVEY PEER GROUP AS THE OFFICIAL CORNER UNDER P.A. 345 OF 1990 AT A MEETING HELD ON // 10-79



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set  $5/8" \times 30"$  rebar with alum. cap as witness cor. to meander cor.

Inscribed "x" on S.E. side of light pole S50°W 35.80'

76.82' Set tag in Power Pole

S60°E 43.94' N.W. cor. of green Sided Building (State Wide Real Estate)

3.00' Set PK nail in asphalt sidewalk

Surveyor's Michigan License No. \_

November 10, 1994 \_\_\_ Date \_