

SURVEY & REMONUMENTATION

MAY 07 1997

COMMISSION

1996 IOSCO COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

90-56

For corners in

Iosco

(County)

Located In:

Corner Code ##

1. Public Land Survey

T 22N R 8E

G-9 to G-10 #11

2. Property Controlling
in Section

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. , Recorded Plat

5. Private Claims

STATE OF MICHIGAN
IOSCO COUNTY
FILED

5 NOV 96 4:31 P.M.

RONITA M. COYLE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, James H. Granger, in a field survey on October 25, 19 96,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:

1843 GLO John Mullett

Set Wood Post

8" W. Pine

N 22° W

54 lks

12" Cottonwood

N 73° E

65 lks

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original evidence found. Reestablished position by single proportionate measurement
on a straight line extension of the W. line of Sec. 22.

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 10-23-96

James H. Granger

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" x 30" rebar w/Remon. Cap

20" Oak

N 40° E

32.73'

nail & tag

12" Red Oak

S 30° E

39.66'

nail & tag

12" Oak

S 10° E

81.55'

nail & tag

Conc. Mon.

South

13.15'

N-S Fence

West

1.77'

Signed by *James H. Granger*

Date October 28, 1996

Surveyor's Michigan License No. 16041