

FEB 16 1999

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

For corners IOSCO Located In: _____ REMONUMENTATION CORNER
Corner Code # _____

1. Public Land Survey T 24N R 9E 5
T _____ R _____
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

98-54

STATE OF MICHIGAN
IOSCO COUNTY
FILED

10 DEC 98 2:55 P.M.

BONITA H. COYLE
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

I, WILLIAM E. WOODS P.S., in a field survey on NOV 17, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1843: ORIGINAL GOVERNMENT NOTES

SET POST

12" Y. PINE S 79° W 14 LK.

10" Y. PINE S 68° W 40 LK.

1944: R.J. COOKE

WEIR WOODLANDS LIBER 4 PAGES 26-28

1961: MAXWELL A. MILES

SUPERVISOR'S PLAT OF NORTHLAND BEACH LIBER 10 PAGES 31-32

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

I SET WITNESS CORNER 656.22 FEET EAST OF 1/4 CORNER
WHICH IS 84.0 FEET EAST OF ORIGINAL MEANDER CORNER.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner

5/8 BAR WITH REMON CAP
TRIPLE 6" MAPLE N 68° W 16.50
8" SPRUCE N 46° W 41.86
4" JACK PINE N 30° E 35.08
4" RED PINE N 85° E 12.77

ACCEPTED BY THE IOSCO COUNTY
SURVEY PEER GROUP AS THE
OFFICIAL CORNER UNDER P.A.
345 OF 1990 AT A MEETING
HELD ON 9-22-98

James H. Stanger



Signed by William E Woods Date 12-9-98

WILLIAM E. WOODS P.S.

Surveyor's Michigan License No. 25882