

SURVEY &
REMONUMENTATION

FORM NO. 985-A



Stock No. 26273

MAR 19 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron
(County)

Located In:

Corner Code #

1. Public Land Survey

T. 41N R. 33W

G-1.2 (002)

2. Property Controlling
in Section

S. T. R.

3. Miscellaneous
Property in Sec.

S. T. R.

4. Lot No. , Recorded Plat

5. Private Claims

Witness Corner

Meander Corner between Sections 3 & 4, T41N R33W

I, Gary L. Pisoni, in a field survey on November 13, 19 96 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Guy H. Carleton, U.S. Deputy Surveyor in 1851.

Original corner: Wood Post

Original bearing trees:

Elm	20"	N 40° E	67 links (44.22 feet)
White Pine	22"	N 14° W	1.25 chns (82.50 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No original corner evidence found.

Found a 1 1/2" dia. Iron pipe marking witness corner meander corner position and 12 feet from waters edge. GLO distance and bearing check good.

I accept the iron pipe as the best available evidence for restoring corner position.

Corner Record Research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Inside the existing iron pipe, I set a 3/4" outside diameter by 3 feet long aluminum rod monument with a 3" cast aluminum cap, stamped to read: Iron County Remonumentation, T41N, R33W, S-4, S-3, W.C., M.C., 1996, RLS-27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Ash	7"	N 15° E	60.33 feet
Ash	8"	N 73° E	67.15 feet
Ash	20"	S 71° E	65.04 feet
Rebar	5/8"x30"	N 37° W	22.50 feet
Steel Sign Post	6'	N 22°W	0.92 feet

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

96 DEC 23 AM 9:11
L.C. Records L. 7, P. 66
Gilbert Stiles
REGISTERED DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

PEER GROUP APPROVED

Gary L. Pisoni 12-11-96
COUNTY REPRESENTATIVE

#96-44

Signed by *Gary L. Pisoni*

Date 12-10-96

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

L. 7 P. 66

