

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 19 T 42N R 31W S 19 T 42N R 31W S _____ T _____ R _____	13 9 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____ _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

13 04/21/2010

9 04/21/2010

I, Stephan J. Szyszkoski, in a field survey on _____ do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 19) Southeast 1/16 corner, Section 19. Not established in the original survey.

(9-Sec. 19) East 1/16 corner, Section 19. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 19) Established the corner at the intersection of straight lines connecting opposite 1/16
corners. The position for the corner falls on the north edge of an E-W two-track road. The monument
cap is set 0.3' below ground.

(9-Sec. 19) Established the corner midway and on a straight line between Quarter corner 1318.02' east
and the intersection of 1/4 lines of Section 19 1318.02' west.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" W.Pine N50E 30.9' mrkd "1/16S BT"
9" J.Pine S50E 30.6' do
6" W.Pine S26W 41.6' do
8" W.Pine N21W 34.4' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Oak S21W 29.2' mrkd "1/16S BT"
9" Maple in clump N85E 20.5' do
12" Oak in clump S83W 43.5' do
12" W.Pine N47W 31.4' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

Signed by

Stephan J. Szyszkoski

Date

05/06/2010

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources and Environment, Forest Management Division



16422

16423