

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF--	LOCATED IN--	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY_____ T. <u>42</u> N. <u>31</u> W.		<u>K7 & L7</u>
2. PROPERTY CONTROLL- <u>24</u> , T. <u>42</u> N. <u>31</u> W. ING IN SECTION_____		<u>1</u>
3. MISCELLANEOUS PROPERTY IN SECTION_____ , T. _____ N. _____ E. S. _____ W.		
4. LOT NO. _____ , RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram - over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corner K7: Sugar post (Not found. L.E.S. control post N44°W 30 lks.)
Y. Birch 12 N48W 20 (Not found. No subsequent accessories found.)
Sugar 10 S60E 37 (" " " " " ")
Corner L7: Sugar post (Not found. L.E.S. control post S23°W 8.2 ft.)
Sugar 8 N13E 25 (Not found. No subsequent accessories found.)
Hemlock 10 S44W 10 (" " " " " ")
Corner 1: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner K7: Re-established 5/23/73 by double proportionate measurement from corners 3 miles N, 2 miles S, 1 mile E, and 1 mile W.
Corner L7: Re-established 6/10/74 on line between Sec. Corners 40.00 ch. to E and to W.
Corner 1: Established 6/10/74 on line between Sec. Cor. 20.00 ch. W and 1/4 cor. 20.00 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner K7: 1" I.D. x 36" iron pipe with 4" aluminum cap.
Sugar Maple 8 S88°E (mag.) 12.2 ft. "S24, NBT"
Sugar Maple 7 S78°W (mag.) 30.7 ft. "S23, NBT"
Sugar Maple 6 N37°W (mag.) 18.4 ft. "S14, NBT"
Corner L7: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Sugar Maple 7 N34°W (mag.) 20.7 ft. "1/4S, NBT"
Sugar Maple 7 S79°E (mag.) 22.1 ft. "1/4S, NBT"
Also squared and scribed a 5" sugar maple S13°W (mag.) 0.8 ft.
Corner 1: 1" I.D. x 36" iron pipe with 3½" aluminum cap.
Tamarack 6 N20°W (mag.) 31.4 ft. "1/16S, BT!"
Tamarack 6 S69°W (mag.) 14.4 ft. "1/16S, BT!"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____ (SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ CHIEF OF SURVEY PARTY DATE _____

APPROVED AND SIGNED BY Arthur O. Enger DATE August 28, 1974
MICHIGAN REGISTERED LAND SURVEYOR

Arthur O. Enger
Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

