

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

| Iron (County) | Located In: | Corner Code # |
|---------------------------------------|------------------|---------------|
| 1. Public Land Survey | T R | |
| | T R | |
| | T R | |
| 2. Property Controlling in Section | S 18 T 43N R 31W | 1 |
| | S 18 T 43N R 31W | 7 |
| | S T R | |
| 3. Miscellaneous Property in Sec. | S T R | |
| | S T R | |
| 4. Lot No. , Recorded Plat | | |
| 5. Private Claims | | |

Register of Deeds Stamp & File Number

| | A | B | C | D | E | F | G | H | I | J | K | L | M |
|----|---|----|---|----|---|----|---|----|---|----|---|----|---|
| 1 | | | | | | | | | | | | | |
| 2 | | 6 | | 5 | | 4 | | 3 | | 2 | | 1 | |
| 3 | | | | | | | | | | | | | |
| 4 | | 7 | | 8 | | 9 | | 10 | | 11 | | 12 | |
| 5 | | | | | | | | | | | | | |
| 6 | | 18 | | 17 | | 16 | | 15 | | 14 | | 13 | |
| 7 | | | | | | | | | | | | | |
| 8 | | 19 | | 20 | | 21 | | 22 | | 23 | | 24 | |
| 9 | | | | | | | | | | | | | |
| 10 | | 30 | | 29 | | 28 | | 27 | | 26 | | 25 | |
| 11 | | | | | | | | | | | | | |
| 12 | | 31 | | 32 | | 33 | | 34 | | 35 | | 36 | |
| 13 | | | | | | | | | | | | | |

I, Stephan J. Szyszkoski, in a field survey on 03/05/13 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(1 - Sec. 18) West 1/16 corner between Sections 7 and 18. Original U.S. plat shows this position to be on the Section line between Section corner 20.08 chains west and Quarter corner 20.00 chains east. Not monumented in the original survey.

(7-Sec. 18) North 1/16 corner between Sections 17 and 18. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1 - Sec. 18) Established the position for the corner on the Section line between Section corner 1325.49' west and Quarter corner 1320.19' east, being proportionate to the original record. Found 2" iron pipe with WMPCO cap N16°E 9.9' distant and not accepted as marking the position for the corner. Removed the WMPCO monument and left it lying adjacent to the monumented position.

(7-Sec. 18) Established the position for the corner midway and on the section line between Section corner 1324.36' north and Quarter corner 1324.26' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(1) Set 1"IDx32" I.pipe with 4" alum. MDNR cap made firm in a mound of rock 3' dia. by 1.5' high. Set measuring nail with MDNR tag in the side of:
3" W.Spruce N26°E 26.8' mrkd "1/16S BT"
8" Cedar in clump N84°W 9.25' do
9" Cedar N53°W 69.5' do
5" Balsam N16°W 7.85' do
Set sq'd cedar post adjacent.
E= 7904382.961 N= 150502.637

(7) Set 5/8"x28" rebar with yellow plastic MDNR cap. Set measuring nail with MDNR tag in:
13" W.Spruce N11°E 8.7' mrkd "1/16S BT"
5" Maple in clump S69°E 58.5' do
10" W.Spruce S17°E 10.6' do
4" Ash N78°W 49.8' do
E= 7905591.003 N= 150085.695

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.635 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 07/18/2013

For the Michigan Department of Natural Resources, Forest Resources Division

