

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 8 T 43N R 31W S 8 T 43N R 31W S _____ T _____ R _____	5 D4 _____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7					9		10		11		12	
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 05/14/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 8) Center North 1/16 corner, Section 8. Not previously monumented.

(D4) Center of Section 8. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 8) Established the position for the corner midway and on a straight line between Center of Section 1335.59' south and Quarter corner (in pond) 1335.59' north. The position for the corner falls in a marsh and is not monumented. Established and monumented a WITNESS CORNER on the N-S 1/4 line 392.15' south of the corner position.

(D4) Established the position for the corner at the intersection of straight lines connecting opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx28" I.pipe with 4" alum. MDNR cap for a WITNESS CORNER 392.15' south of the corner position. Set measuring nail with MDNR tag in the side of:  
10" Cedar N08°E 9.9' mrkd "PCC BT"  
11" W.Spruce S13°W 26.1' do  
12" W.Spruce S66°W 9.1' do  
14" Cedar N01°W 9.0' do  
Set sq'd cedar post adjacent.  
E= 7906416.621 N= 151585.725

(D4) Set 1"IDx28" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:  
6" Maple N67°E 11.1' mrkd "C1/4 BT"  
8" Maple S07°E 30.2' do  
5" Maple S35°W 12.95' do  
5" Maple N67°W 22.3'  
Set sq'd cedar post adjacent.  
E= 7906410.966 N= 151298.267

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum)  
Coord. Ref.=NGS PID RL0240: N= 145070.957 m. E= 7907633.634 m.

Signed by Stephan J. Szyszkoski  
Surveyor's Michigan License No. 33986

Date 06/03/2014

For the Michigan Department of Natural Resources, Forest Resources Division

