SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

SECTION					•••	
		ND CODNED D	ECORDATION CERTIFICATI	F		
	LA Fi	ling Requireme	nt of Act 74, Mich. P.A. 1970	–) rom	MENCING YEAR 2000	
For corners in	• •	iing rioquironia	4 t	RE	CEIVED FOR RECORD	
TO COMOTS III				15.00	H COUNTY, MICHIGAN	
Iron	Locate	d In:	Corner Code #	വവ വ	DEC 22 PM 3: 27	
(County)				1 12 6	11.10P	3.20
1. Public Land Survey	T 43N	I R 31W	C,D-9e	K.C.N	egils: L. 8, P.	0,00
The delice carry	T	R	(010)	تتبيعه	Elle Jack Park	
	T	_ R		مری		
	Τ	_ R			TRIBILA DE RCRUS	
2. Property Controlling S.	T	_ R				
in Section S	T	_ R				
3. Miscellaneous S	<u></u>	_ <u>R</u>		Registe	r of Deeds Stamp & File N	umber
Property in Sec. S.	'	_ R		1,08,000		
4. Lot No, Record	ded Plat			•		
5. Private Claims						
East Meander Corner Between 5	Sections 20 a	nd 29, T43N, R3	1W .			
I, <u>Gary L. Pisoni</u> , in that under requirements of P.A	a field surve	y on <u>Decemb</u>	the corper points mentioned	A B C	DEFGHIJ	
in lines 1 and 2 above were	. 74, Michiga in conformar	nce with regulat	ions and rules therefore as	2 - 6	5 4 3 2	-
required in the current manual	of survey inst	tructions of the l	Inited States Department of	3		
the Interior Rureau of Land Mar	nagement or b	by a decree of a (Court of Law and for that the	4 - 7 -	891011-	12
corner points mentioned in line the Michigan Board of Land S	s 3, 4 and 5	above were in co	Court of Law established	5		
re-established, monumented, re	covered, four	nd as expressed t	elow:	6 -18	-17-16-1-15-1-14-	13
				7		
NOTE: Not more than 2 corners,	all in the same	town and range, r	may be recorded		20212223	24
on this certificate.				819		T 1
		•		9		
				10 - 30	_2928	25
				11		
A. Description of original mon	ument and ac	ccessories and/or	subsequent restoration:	12 - 31	32333435	36
Original corner established	on July 16 1	1949 by John Ru	rt IIS Denuty Surveyor.	131		
Original Corner; Wood pos		1040 by Joini Du	it, o,o. Dopaty carrayan			
Original Bearing Trees:			77 N. J. (50 00 to 1)			
Black Ash	10"	N 03°E S 53° E	77 links (50.82 feet) 44 links (29.04 feet)			
Oak			·		DEED ODOUB ADDD	つくにし
B. Description of corner evid	ence found a	nd/or method app	olied in restoring or reestablishin	g corner:	PEER GROUP APPR	-30:1-00
No evidence of original B	.T.s found.				COUNTY REPRESENT	
			. 1 to 31 from waters adap		, , , , , , , , , , , , , , , , , , ,	
			ver and is 7' from waters edge.			
Restored the corner posit	tion by single	proportionate me	casurement and set a witness c	orner mear	der corner on line betwee	en the
Northwest Section corne	r and the Nor	th Quarter corne	r of Section 29.			
Corner record research o	n file with Co	ounty Representa	tive.			
				the nositio	n of the corner:	
			ablished to perpetuate locating			
At the corner position, se	et a 5/8" dian	neter by 30" long	g rebar pin with a 3" diameter a	luminum ca	ap stamped as follows: In	on Count
Pamanumentation TARN	1 R31W/W/	C.M.C., S- 20, S-	.29. S 89" 51 30" W. 20.59 fee	n, 2000, n	69 27497 HOIII WINGILL	Stabile
the following new bla Ash	azed and scrit 10"	bed bearing trees S 02° W	: (all measurements taken to a r 39.17 feet	11 3106	,	
Ash	6"	N 36° W	4.20 feet			
Spruce	3"	N 55° E	8.35 feet		AND OF MICH.	
Ash	12"	S 49° E S 60° W	32.81 feet 0.85 feet		THE WILLIAM	in.
Steel sign post	_	3 BU W	0.00 1661		GARY L.	
00-088	2		11 10 1.		* PISONI	, T.
Signed by Samy on To	one	Date _	12-19-2000		LAND	J X E
Surveyor's Michigan License N		7	FORM APPROVED BY MICHI	gan state boa	RD OF PROFESSIONAL SURVEYORS, JA	71.28, 1971
,	-				27457 REVISED IN	1983
					EREN INNO SE	1117 1999
					Wall The Pallet	