

SURVEY & REMONUMENTATION

FEB 21 2001

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM12: 50

L.C. Regado: L. 8, P. 209

SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron _____ (County)	Located In:	Corner Code #
1. Public Land Survey	T 43N R 31W	C-8
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

I, Robert A. Goodreau in a field survey on March 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

C-8 Original corner established by John Burt, U.S. Deputy Surveyor, on 14 July 1849.

Original witnesses: Y. Birch 14 S65E 28 links
Y. Birch 14 N60W 7 links

Billy D. Buckler RLS replaced found small squared wood post w/ a 1" iron pipe w/ 4" brass cap on 19 September 1960. The corner position checked w/ existing fence lines and other corner locations in the area (Liber 2, Page 292).

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-8 Found corner as described by Buckler.

Found stumps of witnesses recorded by Buckler as:

10" Aspen (1/4S NBT) N 40° E 29 links
10" Aspen (1/4S NBT) S 42° E 23 links

Corner record research on file with county representative.

PEER GROUP APPROVED

Ken Hufsch. Perm 11-14-2000
COUNTY REPRESENTATIVE


C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-8 Accepted corner as found.

NEW witnesses: 5" Ash N 35° W 12.72'
5" Ash S 05° W 24.85'
6" W. Birch N 69° W 48.50'
Sign post S 60° W 1.40'
Power pole WEPCO #00-02277

Note: Measurements taken to a nail in side of witness.

S 29° E 33.25'



Signed by RAV
Surveyor's Michigan License No. 43053

Date July 1, 2000