

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12: 50

L.C. Records: L.S. P. 210

*Robert A. Goodreau*  
REGISTERED PROFESSIONAL SURVEYOR

For corners in

_____ Iron _____	Located In:	Corner Code #
(County)		
1. Public Land Survey	T <u>43N</u> R <u>31W</u>	<u>C-9</u>
	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling	S _____ T _____ R _____	_____
in Section	S _____ T _____ R _____	_____
3. Miscellaneous	S _____ T _____ R _____	_____
Property in Sec.	S _____ T _____ R _____	_____

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, Robert A. Goodreau in a field survey on March 21, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

#### A. Description of original monument and accessories and/or subsequent restoration:

C-9 Original corner established by John Burt, U.S. Deputy Surveyor, on 14 July 1849.

Original witnesses: Cedar 10 S43W 16 links  
Y. Birch 10 N52E 16 links

Keith L. Sackett RLS restored corner w/ 1" ID iron pipe on 20 May 1985 using double proportionate measurement (Liber 5, Page 93).

#### B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-9 Found corner as described by Sackett..

Found witnesses recorded by Sackett as: 12" Cedar N 76° W 7.6' S19, NBT  
12" Cedar S 01° E 9.0' S29, NBT (incorrect I.D., actually W. Spruce)  
Power pole N 44° E 44.3'

Corner record research on file with county representative.

PEER GROUP APPROVED

*Iron County Rep* 11-14-2000  
COUNTY REPRESENTATIVE

#### C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C-9 Accepted corner as found.

Witnesses: Set 16d nails in above witnesses at recorded distances.  
5" Fir S 50° E 57.13'  
Sign post South 3.70'

Note: Measurement taken to a nail in side of witness.

Signed by *R.A. Goodreau*

Date July 1, 2000

Surveyor's Michigan License No. 43053

