

SURVEY & REMONUMENTATION

JAN 19 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey	<u>T 43N R 33W</u>	<u>K-11</u>
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
	T <u> </u> R <u> </u>	
2. Property Controlling in Section	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	
3. Miscellaneous Property in Sec.	S <u> </u> T <u> </u> R <u> </u>	
	S <u> </u> T <u> </u> R <u> </u>	

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

98 DEC 28 AM 11:24
L.C. Records: L. 7, P. 311
[Signature]
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

Section Corner Sections 25, 26, 35 and 36, T43N, R33W

I, Gary L. Pisoni, in a field survey on Dec. 14, 1998 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in September, 1851 by Guy H. Carleton, Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Yellow Birch	12"	S 20° W	11 lks (7.26 feet)
Sugar	12"	N 55° E	25 lks (16.5 feet)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found. Found a 1 1/4" diameter iron bar, 6" above ground surface and located on a fence line running South and West and a rock fence line to the North.

I accept the above iron bar as the best available evidence for restoring the corner position.

Distances to adjoining corners are consistent with GLO distances.

Corner record research on file with County Representative.

PEER GROUP APPROVED

Iron A. Pisoni 12-18-98
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

From the above described corner position (iron bar), I set a reference monument, being a 5/8" diameter by 30" long rebar, with a 3" aluminum cap stamped as follows:

Iron County Remonumentation, T43N, R33W, R.M., S-25, S-26, S-35, S-36, S 32° W, 1.40', 1998, RLS 27457, from which I blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Sugar Maple	12"	S 33°W	35.06 feet
Sugar Maple	13"	S 89°W	37.66 feet
Sugar Maple	12"	N 28°W	28.80 feet
R.M.	5/8" x 30" rebar	N 32°E	1.40 feet
Steel sign post		N 32°E	2.0 feet

98-106

Signed by

[Signature]

Date 12-21-98

Surveyor's Michigan License No: 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 25, 1971
27457 REVISED, MAY 24, 1975
REVISED, JAN., 1983
REVISED, OCT., 1995



L. 7 P. 311