

MAR 09 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	<u>Iron</u> (County)	Located In:	Corner Code #
1. Public Land Survey		T <u>43N</u> R <u>34W</u>	<u>B-13</u> ✓
		T <u>42N</u> R <u>34W</u>	<u>B-1</u>
		T _____ R _____	_____
		T _____ R _____	_____
2. Property Controlling In Section	S _____	T _____ R _____	_____
	S _____	T _____ R _____	_____
3. Miscellaneous	S _____	T _____ R _____	_____
Property in Sec.	S _____	T _____ R _____	_____

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD

99 DEC 30 AM 10:26

L.C. Records: L.8, P.93

Robert J. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

Quarter Corner to Section 31, T43N, R34W

Quarter Corner to Section 6, T42N, R34W

I, Gary L. Pisoni, in a field survey on Oct. 1, 1999 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6			5			4		3		2		1
3													
4	7			8			9		10		11		12
5													
6	18			17			16		15		14		13
7													
8	19			20			21		22		23		24
9													
10	30			29			28		27		26		25
11													
12	31			32			33		34		35		36
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on September 8, 1846 by William A. Burt, U.S. Deputy Surveyor.

Original Corner; Fir Post

Original Bearing Trees:

Yellow Birch	16"	N 29° E	35 lks (23.10 feet)
Yellow Birch	12"	N 49° W	32 lks (21.12 feet)

PEER GROUP APPROVED

Iron County Rep. 12-21-99
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Found a 1" diameter iron pin located 8' North of the centerline of an existing road known as Lover's Lane which runs East and West. Iron pin was set by local mining company. Iron pin is consistent with GLO distances East and West.

I accept the iron pin as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set two (2) reference monuments being a 5/8" diameter by 30" long rebar pin with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R34W, R.M., 1/4, S-31, S-6, T42N, N 45°W, 47.45 feet, 1999, RLS 27457; T43N, R34W, R.M., 1/4, S-31, S-6, T42N, South, 18.40 feet, 1999, RLS 27457 from which I established the following new blazed and scribed bearing trees or reference objects:

Popple	7"	N 44° E	47.00 feet
R.M.	5/8"x30" rebar	S 45° E	47.45 feet
Red Pine	11"	S 37° W	58.46 feet
R.M.	5/8" x 30" rebar	North	18.40 feet
Steel sign post		North	19.15 feet

99-93

Signed by *Gary L. Pisoni* Date 12-28-99Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995

